UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS Carlsbad Field Office

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals. OCD-Artesia

SUBMIT IN TRIPLICATE - Other instructions on page 2

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

5. Lease Serial No.
NMLC028784C

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.
NMNM88525X

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

8. Well Name and No.
BURCH KEELY UNIT 940H

2. Name of Operator
COG OPERATING LLC
Contact: SANDY BALLARD
E-Mail: sballard@concho.com

9. API Well No.
30-015-44080-00-S1

3a. Address
600 W ILLINOIS AVENUE
MIDLAND, TX 79701

3b. Phone No. (include area code)
Ph: 432-686-4373

10. Field and Pool or Exploratory Area
BURCH KEELY-GLORIETA-UPR YESO

4. Location of Well *(Footage, Sec., T., R., M., or Survey Description)*

Sec 13 T17S R29E SENE 1650FNL 195FEL
32.837135 N Lat, 104.019783 W Lon

11. County or Parish, State
EDDY COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	☐ Well Integrity
☒ Subsequent Report	☐ Casing Repair	☐ New Construction	☐ Recomplete	☒ Other
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	Venting and/or Flaring
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Burch Keely Unit #940
Burch Keely 13a
Actual gas flared for this battery for 3/1/2018 TO 5/30/2018 is as follows:
(Permit approval: Electronic Submission (#404837)
March
Total for Battery = 0 MCF
April
Total for Battery = 0 MCF
May
Total for Battery = 1369 mcf

Number of wells to flare: (21)

NM OIL CONSERVATION
ARTESIA DISTRICT
DEC 12 2018
Accepted for record
NMOCD   RECEIVED

14. I hereby certify that the foregoing is true and correct.
Electronic Submission #445352 verified by the BLM Well Information System
For COG OPERATING LLC, sent to the Carlsbad
Committed to AFMSS for processing by PRISCILLA PEREZ on 11/29/2018 (19PP0465SE)

Name *(Printed/Typed)* SANDY BALLARD

Title SENIOR ADMINISTATIVE ASSISTANT

Signature (Electronic Submission)

Date 11/28/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved By

Title			Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office NOV 30 2018 /s/ Jonathon Shepard

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. LAND MANAGEMENT
CARLSBAD FIELD OFFICE

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #445352 that would not fit on the form

32. Additional remarks, continued

BURCH-KEELY UNIT 420 30-015-36180
BURCH-KEELY UNIT 505 30-015-39438
BURCH-KEELY UNIT 508 30-015-39313
BURCH-KEELY UNIT 509 30-015-39439
BURCH-KEELY UNIT 512 30-015-39314
BURCH-KEELY UNIT 513 30-015-39440
BURCH-KEELY UNIT 517 30-015-39441
BURCH-KEELY UNIT 519 30-015-40690
BURCH-KEELY UNIT 520 30-015-39315
BURCH-KEELY UNIT 524 30-015-39518
BURCH-KEELY UNIT 525 30-015-39754
BURCH-KEELY UNIT 527 30-015-40315
BURCH-KEELY UNIT 530 30-015-39519
BURCH-KEELY UNIT 531 30-015-40316
BURCH-KEELY UNIT 532 30-015-40317
BURCH-KEELY UNIT 533 30-015-40318
BURCH-KEELY UNIT 536 30-015-39520
BURCH-KEELY UNIT 930H 30-015-40969
BURCH-KEELY UNIT 931H 30-015-42761
BURCH-KEELY UNIT 933H 30-015-40970
BURCH-KEELY UNIT 940H 30-015-44080
Reason for flare: UNPLANNED MIDSTREAM CURTAILMENT PLANT MAINTENANCE AND HLP