N. M. O. C. C. COPY

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE* (Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL [X] GAS WELL [ ] OTHER

2. NAME OF OPERATOR: Shelly Oil Company

3. ADDRESS OF OPERATOR: Box 730 - Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface: 1980' FSL & 1980' FWL Sec. 15-17S-31E

5. LEASE DESIGNATION AND SERIAL NO.: LC 029420 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME:

7. UNIT AGREEMENT NAME: Shelly Unit

8. FARM OR LEASE NAME: Shelly Unit

9. WELL NO.: 27

10. FIELD AND POOL, OR WILDCAT: Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA: Sec.15-17S-31E

12. COUNTY OR PARISH: Eddy

13. STATE: New Mexico

14. PERMIT NO.: -

15. ELEVATIONS (Show whether DF, RT, GR, etc.): 3870' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	[ ]	PULL OR ALTER CASING	[ ]	WATER SHUT-OFF	[ ]	REPAIRING WELL	[ ]
FRACTURE TREAT	[ ]	MULTIPLE COMPLETE	[ ]	FRACTURE TREATMENT	[ ]	ALTERING CASING	[ ]
SHOOT OR ACIDIZE	[ ]	ABANDON*	[ ]	SHOOTING OR ACIDIZING	[ ]	ABANDONMENT*	[ ]
REPAIR WELL	[ ]	CHANGE PLANS	[ ]	(Other)			
(Other) Perforate & treat			[X]	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Well is presently producing from open hole section 3491-3600' of the San Andres formation.

We propose to perforate and treat the Grayburg Formation as follows:

1. Move in and rig up Pulling Unit.
2. Pull rods and tubing.
3. Selectively perforate 5-1/2" OD casing from 3203-3453' (intervals) in the San Andres Formation with 16 shots.
4. Isolate and treat through 5-1/2" OD casing perfs. 3203-3453' (intervals) with 1000 gals. acid.
5. Isolate and fracture through 5-1/2" OD casing perfs. 3203-3453' (intervals) with 20,000 gals. water and 20,000# 20/40 sand.
6. Pull retrievable bridge plug.
7. Run tubing and rods and return well to a producing status.

RECEIVED
AUG 8 1967
O. C. C.
ARTESIA, OFFICE

RECEIVED
AUG - 7 1967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED (ORIGINAL) W. E. Fletcher TITLE District Superintendent DATE August 4, 1967.

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
AUG - 7 1967
R. L. BEEKMA
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963—O-689229

647-851

RECEIVED

ADDED