UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other Instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 7509

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL WELL [x]   GAS WELL [ ]   OTHER

2. NAME OF OPERATOR

Basin Fuels, Ltd.

3. ADDRESS OF OPERATOR

P. O. Box 50, Farmington, N.M. 87499

4. LOCATION OF WELL. (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660 FNL & 660 FWL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Scooter

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Franciscan Lake Mesa Verde

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 18, T20N, R5W, N.M.P.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6729 GL

12. COUNTY OR PARISH
McKinley

13. STATE
N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF [ ]
FRACTURE TREAT [ ]
SHOOT OR ACIDIZE [ ]
REPAIR WELL [ ]
(Other)

PULL OR ALTER CASING [ ]
MULTIPLE COMPLETE [ ]
ABANDON* [ ]
CHANGE PLANS [ ]

SUBSEQUENT REPORT OF:

WATER SHUT-OFF [ ]
FRACTURE TREATMENT [ ]
SHOOTING OR ACIDIZING [ ]
(Other) See below
(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL [ ]
ALTERING CASING [ ]
ABANDONMENT* [ ]

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Request this well be placed in inactive status. This well has not produced for the
preceeding ninety (90) days, but prior to going down because of a defective pump,
the same was making approximately 2 barrels per day. Cannot afford to repair this
well at current crude oil prices of $12.75 per barrel. Substantial reserves remain
in subject well, but can only be recovered at higher oil prices. In addition, other
zones behind the pipe remain untested.

Casing in subject well is sound and no contamination of other formations is contemplated.

THIS APPROVAL EXPIRES DEC 01 1989

RECEIVED
DEC 06 1988
OIL CON. DIV.
DIST. 3

88 NOV 25 PM 1:11
FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE Owner
Joel B. Burr, JR.

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DATE 11/15/88

DEC 01 1988
DATE

AREA MANAGER
FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side

NMOCC