DISTRIBUTION		
SANTA FE	1	
FILE	1	
U.S.G.S.		
LAND OFFICE		
OPERATOR	5	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State [X]	Fee ☐

5. State Oil & Gas Lease No.

E - 6597 - 2

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)

1.

OIL WELL [X]   GAS WELL ☐   OTHER-

7. Unit Agreement Name

2. Name of Operator

Hixon Development Company

8. Farm or Lease Name

Central Bisti State

3. Address of Operator

P. O. Box 2810, Farmington, New Mexico

9. Well No.

41

4. Location of Well

UNIT LETTER __D__ , __660__ FEET FROM THE __North__ LINE AND __660__ FEET FROM

THE __West__ LINE, SECTION __16__ TOWNSHIP __25N__ RANGE __12W__ NMPM.

10. Field and Pool, or Wildcat

Undesignated

15. Elevation (Show whether DF, RT, GR, etc.)

6252' KB

12. County

San Juan

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER _____

PLUG AND ABANDON ☐
CHANGE PLANS ☐
☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER __Commence plug back operations__ [X]

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well is being recompleted from the Lower Gallup to the Mesaverde - Point Lookout. Commenced recompletion operations 12-10-76. Ran guage ring and junk basket. Fished parted tubing string. Ran casing inspection log surface to 4000'. Set packer for 5 1/2" 15.5# casing @ 3990' KB to isolate Lower Gallup perforations 4758'-4857'. Perforated 4 cement holes @ 3770'. Old cement top @ 3785'. Run tubing and cement retainer. Set retainer @ 3637' KB. Cement casing with 50 sacks cement. Trip in with bit and scraper. Drill out retainer and cement. Perforate Lower Point Lookout Zone 4-JSPF @ 3743'-46' and 3733'-37'. Swab tested zone at 0.8 BFPH with trace of oil. Acidized perforations with 500 gallons 15% acid. ISIP - 850 psi. Swab tested well at 8.3 BFPH with show of oil. Shut well in pending pumping unit installation. The well will be pump tested into separate facilities in order to determine it commercial.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE __Petroleum Engineer__ DATE __2-7-77__

Original Signed by A. R. Kendrick

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: