Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

~~NM-036254~~ S F 078056

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1.

OIL WELL [X]	GAS WELL [ ]	OTHER	

2. NAME OF OPERATOR

Hixon Development Company

3. ADDRESS OF OPERATOR

P.O. Box 2810, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FSL, 1980' FWL, Section 6, T25N, R12W

7. UNIT AGREEMENT NAME

Central Bisti Unit

8. FARM OR LEASE NAME

9. WELL NO.

WI-11

10. FIELD AND POOL, OR WILDCAT

Bisti Lower Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Section 6, T25N, R12W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6200' GLE

12. COUNTY OR PARISH: San Juan   13. STATE: NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF [ ]	PULL OR ALTER CASING [ ]
FRACTURE TREAT [ ]	MULTIPLE COMPLETE [ ]
SHOOT OR ACIDIZE [ ]	ABANDON* [ ]
REPAIR WELL [ ]	CHANGE PLANS [ ]
(Other) Convert well to production [XX]	

SUBSEQUENT REPORT OF:

|	
WATER SHUT-OFF [ ]	REPAIRING WELL [ ]
FRACTURE TREATMENT [ ]	ALTERING CASING [ ]
SHOOTING OR ACIDIZING [ ]	ABANDONMENT* [ ]
(Other) _____	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is planned to convert this water injection well to production as follows:
1) Clean out wellbore to PBD
2) Acidize well with 1000 gallons 15% acid
3) Put well on pump with rods and insert pump
4) Test and evaluate

18. I hereby certify that the foregoing is true and correct

SIGNED _____   TITLE Petroleum Engineer   DATE 12-19-80

(This space for Federal or State office use)

APPROVED BY _____   TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JAN 5, 1981.

James F. Sims
JAMES F. SIMS
DISTRICT OIL & GAS SUPERVISOR

*See Instructions on Reverse Side