Submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
070 FARMINGTON, NM
96 MAR -1 PM 2:01

Sundry Notices and Reports on Wells

RECEIVED
MAR - 7 1996
OIL CON. DIV.
DIST. 3

1. **Type of Well**
GAS

5. **Lease Number**
SF-078487C

6. **If Indian, All. or Tribe Name**

7. **Unit Agreement Name**

2. **Name of Operator**
MERIDIAN OIL

8. **Well Name & Number**
Sunray #3

3. **Address & Phone No. of Operator**
PO Box 4289, Farmington, NM 87499 (505) 326-9700

9. **API Well No.**
30-045-08754

4. **Location of Well, Footage, Sec., T, R, M**
1750'FNL, 1150'FWL, Sec.5, T-29-N, R-8-W, NMPM

10. **Field and Pool**
Blanco Pictured Cliffs

11. **County and State**
San Juan Co, NM

12. **CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA**

Type of Submission	Type of Action		
___ Notice of Intent	_X_ Abandonment	___ Change of Plans	
	___ Recompletion	___ New Construction	
_X_ Subsequent Report	___ Plugging Back	___ Non-Routine Fracturing	
	___ Casing Repair	___ Water Shut off	
___ Final Abandonment	___ Altering Casing	___ Conversion to Injection	
	___ Other -		

13. **Describe Proposed or Completed Operations**

2-21-96 MIRU. Pump 32 bbl wtr down csg. No flow out bradenhead. Plug #1: pump 31 sx Class "B" cmt into Pictured Cliffs perfs. Displaced to 2000'. Sqz to 300 psi. WOC. SDON.

2-22-96 Load hole w/5 bbl wtr. PT csg to 500 psi, failed. TIH, tag TOC @ 2881'. TOOH. Establish injection, no flow out bradenhead. Plug #2: pump 31 sx Class "B" cmt into Pictured Cliffs perfs. Displace to 2000'. Sqz to 200 psi. WOC. Load hole w/3 bbl wtr. PT csg to 1000 psi, OK. TIH, tag TOC @ 2420'. Perf 4 sqz holes @ 1989'. TOOH. Establish injection. Plug #3: pump 140 sx Class "B" cmt @ 1725-1989'. Displaced to 1675'. Sqz to 500 psi. WOC. SDON.

2-26-96 TIH, tag TOC @ 1550'. Perf 2 sqz holes @ 592'. Establish injection. Plug #4: pump 55 sx Class "B" cmt w/2% calcium chloride @ 492-592'. Displace to 410'. Sqz to 800 psi. WOC. TIH, tag TOC @ 408'. Perf 2 sqz holes @ 156'. TOOH. Establish circ down csg & out bradenhead w/10 bbl wtr. Plug #5: pump 60 sx Class "B" cmt down csg & out bradenhead. Circ 1 bbl cmt to surface. WOC. ND BOP. Cut off WH. Install dry hole marker w/10 sx Class "B" cmt. RD. Rig released. Well plugged and abandoned 2-26-96.

14. **I hereby certify that the foregoing is true and correct.**

Signed Peggy Bradfield Title Regulatory Administrator Date 2/28/96

(This space for Federal or State Office use)
APPROVED BY _____ Title _____ Date _____
CONDITION OF APPROVAL, if any:

APPROVED
MAR 04 1996
DISTRICT MANAGER

NMOCD