Form 3160–5
(November 1983)
(Formerly 9–331)

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

5. LEASE DESIGNATION AND SERIAL NO.

SF-080517

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

N/A

1.
OIL WELL ☐   GAS WELL ☒   OTHER

7. UNIT AGREEMENT NAME

N/A

2. NAME OF OPERATOR

Union Texas Petroleum

8. FARM OR LEASE NAME

PAYNE

3. ADDRESS OF OPERATOR

375 US Highway 64, Farmington, NM 87401

9. WELL NO.

11

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

590' FNL & 810' FEL

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 27, T32N-R10W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

12. COUNTY OR PARISH
San Juan

13. STATE
NM

16.
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	
SHOOT OR ACIDIZE ☐	ABANDON* ☐	
REPAIR WELL ☐	CHANGE PLANS ☐	
(Other)		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐	
FRACTURE TREATMENT ☐	ALTERING CASING ☐	
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒	
(Other) _Well status_		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In response to your letter referenced SF-080517 (WC), 3162.3-1.0 (019), Union Texas Petroleum wishes to advise:

1. The subject well has been completed. However, during the completion the well developed problems with the liner hanger.
2. Due to lease stipulations (Bald Eagle) we were unable to move back on the well.
3. A remedial plan will be developed and the liner hanger repaired as soon as surface occupancy is permitted pursuant to our lease.

18. I hereby certify that the foregoing is true and correct.

SIGNED _Robert C. Frank_   TITLE _Permit Coordinator_   DATE _4/23/88_

(This space for Federal or State office use)

APPROVED BY _____   TITLE _____   DATE _____
CONDITIONS OF APPROVAL, IF ANY:

See Instructions on Reverse Side

NMOCC