Form 3160-5
(June 1990)

RECEIVED
APR 19 8 24 AM '93

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

LC-069300

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

1. Type of Well

[X] Oil Well   [ ] Gas Well   [ ] Other

2. Name of Operator

Discovery Operating, Inc.

3. Address and Telephone No.

800 N. Marienfeld, Suite 100, Midland, Tx   79701

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter D, 660' from the North line and 660' from
the West line, Section 10, Township 9S, Range 36E

8. Well Name and No.   #1

Mobil Atlantic Federal

9. API Well No.

30-025-23362

10. Field and Pool, or Exploratory Area

Allison-Penn

11. County or Parish, State

Lea County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
[ ] Notice of Intent	[ ] Abandonment	[ ] Change of Plans
	[ ] Recompletion	[ ] New Construction
[ ] Subsequent Report	[ ] Plugging Back	[ ] Non-Routine Fracturing
	[ ] Casing Repair	[ ] Water Shut-Off
[X] Final Abandonment Notice	[ ] Altering Casing	[ ] Conversion to Injection
	[X] Other Plug & Abandon	[ ] Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Unable to get to the perforation with CIBP
2. Spot 40 sacks cement with tubing above perfs. WOC and tag top plug @ 9540'
3. Displaced hole with 25 ppg mud.   ppb ?
4. Pulled out 4237' of 4 1/2" casing.
5. Spot 40 sack plug @4263'. WOC and tag top of plug at 4220'.
6. Spot 40 sack plug @ 4200'. WOC and tag top of plug @ 4061'.
7. Pulled out 580' 8 5/8" casing.
8. Spot 140 sack plug at 620'. WOC and tag top of plug @ 348'.
9. Loaded hole with mud 348' to surface.
10. Spot 20 sack plug 50' to surface.
11. Cut off wellhead, weld on plate and dry hole marker, clear location.

14. I hereby certify that the foregoing is true and correct

Signed _____   Title Production Clerk   Date 4/16/93

(This space for Federal or State office use)

Approved by _____ (ORIG. SGD.) JOE C. LARA   Title PETROLEUM ENGINEER   Date APR 27 1993

Conditions of approval, if any:

*See Instruction on Reverse Side