




Case No.

1904

Large Exhibits








- GOR DECREASED
 ○ GOR INCREASED
 ○ GOR REMAINED ABOUT THE SAME

LEGEND



- ⊙ LPG INJECTION WELL
 △ GAS INJECTION WELL
 • DRILLED AFTER UNITIZATION
 □ WATER INJECTION WELL


CENTRAL BISTI LOWER GALLUP SAND UNIT
San Juan County, New Mexico




SUNRAY MID-CONTINENT OIL COMPANY
EXHIBIT NO. 5 CASE NO. 122










- PRODUCTION CAPACITY INCREASED
- PRODUCTION CAPACITY DECREASED
- PRODUCTION CAPACITY ABOUT THE SAME

LEGEND

- ⊙ LPG INJECTION WELL
- △ GAS INJECTION WELL
- DRILLED AFTER UNITIZATION
- WATER INJECTION WELL

CENTRAL BISTI LOWER GALLUP SAND UNIT San Juan County, New Mexico



SUNRAY MID-CONTINENT OIL COMPANY
EXHIBIT NO. 1 CASE NO. 1204

