NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State [X] Fee [ ]

5. State Oil & Gas Lease No.
E-291-3

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL [ ] GAS WELL [X] OTHER-

7. Unit Agreement Name

2. Name of Operator
El Paso Natural Gas Company

8. Farm or Lease Name
Southern Pet. Co,

3. Address of Operator
P. O. Box 289, Farmington, New Mexico 87401

9. Well No.
4

4. Location of Well
UNIT LETTER K, 1450 FEET FROM THE South LINE AND 1450 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 26N RANGE 6W NMPM.

10. Field and Pool, or Wildcat
Undesignated Chacra

15. Elevation *(Show whether DF, RT, GR, etc.)*
6732' GR

12. County
Rio Arriba

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK [ ]	PLUG AND ABANDON [ ]	REMEDIAL WORK [ ]	ALTERING CASING [ ]
TEMPORARILY ABANDON [ ]		COMMENCE DRILLING OPNS. [ ]	PLUG AND ABANDONMENT [X]
PULL OR ALTER CASING [ ]	CHANGE PLANS [ ]	CASING TEST AND CEMENT JOB [ ]	
OTHER [ ]		OTHER [ ]	

17. Describe Proposed or Completed Operations *(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)* SEE RULE 1103.

Oct. 16, 17- 1981

1. Pull tubing after backing off packer. Remove packer hanger and run tubing leak in hole. Circulate.
2. Spot 100' plug on top of packer. (6 sx). Perforate 2 squeeze holes and
3. Spot 100' plug 2820' to 2720' inside and outside casing.
4. Perforate 2 squeeze holes at 2350' and spot 54 sx cement plug to cover Ojo Alamo 2380' to 2100'.
5. Perforate at 550' and spot 100' cement plug inside and outside casing 550' to 450'.
6. Perforate 2 squeeze holes 185' and spot 100' plug to 85'.
7. Spot 10 sx cement plug at surface and set dry hole marker.
8. Comply general requirement. Site ready for inspection

RECEIVED
NOV 2 - 1981
OIL CON. COM.
DIST. 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A R Bowman TITLE Production Engineer DATE 10-23-81

Original Signed by Jeff Edmister

APPROVED BY _____ TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE NOV 2 1981

CONDITIONS OF APPROVAL, IF ANY: