Form 3160-5
(April 2004)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- *Other instructions on reverse side.*

5. Lease Serial No. NMNM 45236
6. If Indian, Allottee or Tribe Name
7. If Unit or CA/Agreement, Name and/or No.
8. Well Name and No. Sterling Silver 33 Federal #1H
9. API Well No. 30-015-39831
10. Field and Pool, or Exploratory Area Ingle Wells Bone Spring
11. County or Parish, State Eddy NM

1. Type of Well: ☑ Oil Well ☐ Gas Well ☐ Other
2. Name of Operator: OXY USA Inc. 16696
3a. Address: P.O. Box 50250 Midland, TX 79710
3b. Phone No. (include area code): 432-685-5717
4. Location of Well (Footage, Sec, T, R, M, or Survey Description)
S-360 FSL 590 FEL SESE(P) Sec 33 T23S R31E
BH-330 FNL 649 FEL NENE(A) " " "

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☑ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☑ Other Completion
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

RUPU 5/25/12, Drill and clean out to PBTD @ 14197'. Pressure test csg to 6280', held for 30min, tested good. Perf @ 13511-13030, 12870-12390, 12230-11750, 11590-11110, 10950-10470' Total 190 holes. Frac w/ 294459g Water Frac GR 8 followed by 21000g 15% HCl acid followed by 1267942g Delta Frac 200 R-20 w/ 1501311# sand, RD Halliburton. Swab, flow back to clean up well and test well for potential.

HWade 9/18/12
Accepted for record
NMOCD

RECEIVED
SEP 18 2012
NMOCD ARTESIA

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed): David Stewart
Title: Regulatory Advisor
Signature:
Date: 9/11/12

ACCEPTED FOR RECORD
SEP 15 2012
BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by: Title: Date:
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office:

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)