UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL. "E"
(Other Instructions on verse side)

Drawer DD
Artesia, NM 88210

RECEIVED

APR 26 89

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO
LC-029426-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1.
OIL WELL [X]   GAS WELL [ ]   OTHER

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

Hondo Oil & Gas Company

8. FARM OR LEASE NAME
H. E. West "B"

3. ADDRESS OF OPERATOR

P. O. Box 2208, Roswell, NM 88202

9. WELL NO.
20

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 1980' FEL

10. FIELD AND POOL, OR WILDCAT
Grayburg Jackson SR-2-6-SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec.10-T17S-R31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3906' GL

12. COUNTY OR PARISH
Eddy

13. STATE
NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF		PULL OR ALTER CASING	
FRACTURE TREAT		MULTIPLE COMPLETE	
SHOOT OR ACIDIZE		ABANDON*	
REPAIR WELL		CHANGE PLANS	
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF		REPAIRING WELL	
FRACTURE TREATMENT		ALTERING CASING	
SHOOTING OR ACIDIZING	X	ABANDONMENT*	
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4/13/89   Top of liner @ 3175' and top of cement @ 3396'. Spotted 5 bbls. cement at liner top. Squeezed liner top.

4/15/89   Drilled cement from 3075' to top of liner @ 3175'. Cleaned out liner. Perforated 17 holes from 3858-3937'.

4/16/89   Acidized 3858-3937' with 2000 gal. 15% NEFE acid. Swabbed well back.

4/18/89   Reacidized 3858-3937' with 4000 gal. 20% CRA acid. Swabbed well back.

18. I hereby certify that the foregoing is true and correct

SIGNED _Lisa Bohannon_   TITLE Engineering Technician   DATE 4/19/89

(This space for Federal or State office use)

APPROVED BY _____   TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
DATE

APR 21 1989

SJS

CARLSBAD, NEW MEXICO

*See Instructions on Reverse Side