Form 3160-5
(August 1999)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

5. Lease Serial No.
NMSF080424

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.
NMNM73345

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

8. Well Name and No.
VAN HOOK LS 1M

2. Name of Operator
BP AMERICA PRODUCTION CO
Contact: CHERRY HLAVA
E-Mail: hlavacl@bp.com

9. API Well No.
30-045-31895-00-X1

3a. Address
P. O. BOX 3092
HOUSTON, TX 77253

3b. Phone No. (include area code)
Ph: 281.366.4081
Fx: 281.366.0700

10. Field and Pool, or Exploratory
BASIN DAKOTA
BLANCO MESAVERDE

4. Location of Well *(Footage, Sec., T., R., M., or Survey Description)*
Sec 27 T32N R11W NESW ~~1820~~1935FSL ~~2490~~1800FWL

11. County or Parish, and State
SAN JUAN COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☒ Other Change to Original A PD
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Original APD submitted on 09/15/2003 and approved on 11/13/2003.

BP America submits for your approval our amended cement report. On 2/10/04 the BLM approved a new surface cement slurry. This new type C slurry with 2% CaCl achieves a compressive strength of 275 psi in 4 hrs and 615 psi in 8 hrs. Therefore all BLM & NMOCD requirements are met to commence N/U operations after 4 hrs. and pressure testing after 8 hrs.

Please see the revised cement program.

FEB 2004

14. I hereby certify that the foregoing is true and correct.
Electronic Submission #27949 verified by the BLM Well Information System
For BP AMERICA PRODUCTION CO, sent to the Farmington
Committed to AFMSS for processing by ADRIENNE GARCIA on 02/19/2004 (04AXG0645SE)

Name *(Printed/Typed)* CHERRY HLAVA — Title AUTHORIZED REPRESENTATIVE

Signature (Electronic Submission) — Date 02/16/2004

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By A G — Title — Date 2-17-04

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. — Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

NMOCD

Cementing Program

Well Name:	Van Hook LS 1M	Field:	Blanco Mesaverde / Basin Dakota
Location:	27-32N-11W, 1935 FSL, 1800 FEL	API No.	
County:	San Juan	Well Flac	
State:	New Mexico	Formation:	Blanco Mesaverde/Basin Dakota
		KB Elev (est)	6374
		GL Elev. (est)	6360

Casing Program:

Casing String	Est. Depth (ft.)	Hole Size (in.)	Casing Size (in.)	Thread	TOC (ft.)	Stage Tool Or TOL (ft.)	Cmt Cir. Out (bbl.)
Surface	120	13.5	9.625	ST&C	Surface	NA	
Intermediate	3403	8.75	7	~~LT&C~~ ST&C	Surface	NA	
Production -	7770	6.25	4.5	ST&C	3303	NA	

Casing Properties: (No Safety Factor Included)

Casing String	Size (in.)	Weight (lb/ft)	Grade	Burst (psi.)	Collapse (psi.)	Joint St. (1000 lbs.)	Capacity (bbl/ft.)	Drift (in.)
Surface	9.625	32	H-40	~~3370~~ 2270	1400	254	0.0787	8.845
Intermediate	7	20	K-55	3740	2270	~~254~~ 234	0.0405	6.456
Production -	4.5	11.6	J-55	5350	4960	154	0.0155	3.875

Mud Program

Apx. Interval (ft.)	Mud Type	Mud Weight
0 - SCP	Water/Spud	8.6-9.2
SCP - ICP	Water/LSND	8.6-9.2
ICP - ICP2	Gas/Air Mist	NA
ICP2 - TD	LSND	8.6 - 9.2

Recommended Mud Properties Prio Cementing:

PV	<20
YP	<10
Fluid Loss	<15

Cementing Program:

	Surface	Intermediate	Production
Excess %, Lead	100	75	40
Excess %, Tail	NA	0	40
BHST (est deg. F)	75	120	183
Special Instructions	1,6,7	1,6,8	2,4,6

1. Do not wash pumps and lines.
2. Wash pumps and lines.
3. Reverse out
4. Run Blend Test on Cement
5. Record Rate, Pressure, and Density on 3.5" disk
6. Confirm densitometer with pressurized mud scales
7. 1" cement to surface if cement is not circulated.
8. If cement is not circulated to surface, run temp. survey 10-12 hr. after landing plug.

Notes:

*Do not wash up on top of plug. Wash lines before displacing production cement job to minmize drillout.

Surface:

Preflush	20 bbl.	FreshWater
Slurry 1	100 sx Class C Cement	
TOC@Surface	+ 2% CaCl2 (accelerator)	

127
~~117~~ cuft

0.4887 cuft/ft OH

Slurry Properties:	Density (lb/gal)	Yield (ft3/sk)	Water (gal/sk)
Slurry 1	15.2	1.27	5.8

Cementing Program

Casing Equipment: 9-5/8", 8R, ST&C
1 Guide Shoe
1 Top Wooden Plug
1 Autofill insert float valve
Centralizers, 1 per joint except top joint
1 Stop Ring
1 Thread Lock Compound

Intermediate:

	Fresh Water	20 bbl	fresh water	
	Lead	290 sx	Class "G" Cement	763 ~~753~~ cuft
	Slurry 1		+ 3% D79 extender	
	TOC@Surface		+1/4 #/sk. Cellophane Flake	
			+ 5 lb/sk Gilsonite	
	Tail	60 sx	50/50 Class "G"/Poz	75 cuft
	Slurry 2		+ 2% gel (extender)	
	500 ft fill		+1/4 #/sk. Cellophane Flake	0.1503 cuft/ft OH
			+ 2% CaCl2 (accelerator)	0.1746 cuft/ft csg ann
			+ 5 lb/sk Gilsonite	

Slurry Properties:	Density (lb/gal)	Yield (ft3/sk)	Water (gal/sk)
Slurry 1	11.4	2.63	15.8
Slurry 2	13.5	1.27	5.72

Casing Equipment: 7", 8R, ST&C

1 Float Shoe (autofill with minimal LCM in mud)
1 Float Collar (autofill with minimal LCM in mud)
1 Stop Ring
Centralizers one in middle of first joint, then every third collar
1 Top Rubber Plug
1 Thread Lock Compound

Production:

	Fresh Water	10 bbl	CW100	
	Lead	190	LiteCrete D961 / D124 / D154	479 ~~472~~ cuft
	Slurry 1		+ 0.03 gps D47 antifoam	
	TOC, 400' above 7" shoe		+ 0.5% D112 fluid loss	
			+ 0.11% D65 TIC	
	Tail	160 sx	50/50 Class "G"/Poz	280 ~~221~~ cuft
	Slurry 2		+ 5% D20 gel (extender)	
	1537 ft fill		+ 0.1% D46 antifoam	
			+ 1/4 #/sk. Cellophane Flake	
			+ 0.25% D167 Fluid Loss	
			+ 5 lb/sk Gilsonite	

Cementing Program

		+0.1% d800, retarder		
		+0.15% D65, dispersant		
				0.1026 cuft/ft OH
Slurry Properties:	Density	Yield	Water	
	(lb/gal)	(ft3/sk)	(gal/sk)	0.1169 cuft/ft csg ann
Slurry 1	9.5	2.52	6.38	
Slurry 2	13	1.44	6.5	Top of Mancos
				5733

Casing Equipment:

4-1/2", 8R, ST&C
1 Float Shoe (autofill with minimal LCM in mud)
1 Float Collar (autofill with minimal LCM in mud)
1 Stop Ring
Centralizers, every 4th joint in mud drilled holes, none in air drilled holes.
1 Top Rubber Plug
1 Thread Lock Compound