Form 9-331a
(Feb. 1951)

APPROVED
OCT 9 1956
JERRY W. LONG
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office Santa Fe
Lease No. NM 021116
Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 17, 19 56

Well No. 2 Redfern is located 1750 ft. from {N/S} line and 960 ft. from {E/W} line of sec. 16

SE/4 16 — (¼ Sec. and Sec. No.)
28N — (Twp.)
11W — (Range)
NMPM — (Meridian)
Fulcher-Kutz Ext. — (Field)
San Juan — (County or Subdivision)
N.M. — (State or Territory)

The elevation of the derrick floor above sea level is 5598 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1582' of 4½", 11 lb. 8 R, casing was cemented on bottom at 1582' with 150SX.

Before drilling the plug on the 4½" casing it held 500# with no pressure drop. After drilling the plug with the use of cable tools the hole was tested by bailing at a total depth of 1584'. After being shut down for 12 hrs. the hole showed no water.

RECEIVED
OCT 10 1956
OIL CON. COM.
DIST. 3

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Redfern & Markham

Address Box 1747

Midland, Texas

By

Title Agent

U. S. GOVERNMENT PRINTING OFFICE 16—8437-6