GW - ____1_____

MONITORING REPORTS

DATE: 2007 - Present



NOTES "MW-XX" – Monitoring Wells Locations
"RW-XX" – Recovery Well Locations
"P" – Piezometer
– Denotes Under Ground Pipe-Way.
– Denotes Above Ground Pipe-Way.
– Denotes Slurry Barrier Wall

"CW" – Collection Well Locations
"OW" – Observation Well Locations
"SW" – Sump Well Locations

REFERENCE DWGS.

NO.	REVISION	JOB No.	DRAWN BY	DATE	CHECKED BY	DATE	APPROVED BY	DATE
8	Revised To Indicate Tanks 24 & 25 Addition.		NHB	3/06				
7	Observation, & Collection Wells Added As Per Enviro. Dept. Mark-Ups.		NHB	12/05				
6	Updated To Indicate Changes As Per Enviro. Dept. Red-Line Mark-Ups.		NHB	7/05				
5	Updated To Indicate Changes As Per Enviro. Dept. Red-Line Mark-Ups.		NHB	3/05				
4	Updated To Indicate Changes As Per Enviro. Dept. Red-Line Mark-Ups.		NHB	2/04				
3	Updated To Indicate Under Ground Pipe Ways In The Tank Farm Area		NHB	12/03				
9	Revised To Indicate "SW" or Sump Well Locations.		NHB	5/06				
1	Updated As Per Enviromental Dept. Mark Up							

SCALE	As Noted	
DRAWN BY	NHB	8/29/02
INITIAL CHK.		
FINAL CHK.		
ENGR.		
APPR. BY		
AFE/WO No.		

Giant Bloomfield Refinery
Area Plot Plan
Recovery Well & Monitoring Well Locations

GIANT REFINING CO.
BLOOMFIELD REFINERY
BLOOMFIELD NEW MEXICO

DWG. NO. D-000-900-023
REV. 9