District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR ☐ Initial Report ☒ Final Report

Name of Company Devon Energy Production	**Contact** Production Assistant Leonard Aguilar
Address 6488 Seven Rivers Hwy Artesia, NM 88220	**Telephone No.** 575.513.1930
Facility Name Pure Gold C-17 Federal 4	**Facility Type** Oil

Surface Owner Federal	**Mineral Owner** Federal	**API No.** 30-015-27153

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	17	23S	31E	1780	FNL	330	FEL	Eddy

Latitude: 32.306709 **Longitude:** -103.791939

NATURE OF RELEASE

Type of Release Spill Oil	**Volume of Release** 200 BBL	**Volume Recovered** 185 BBL
Source of Release Water dump clogged and sent oil to oil tank	**Date and Hour of Occurrence** 10/08/15 at 10:30am	**Date and Hour of Discovery** 10/08/15 at 10:30am
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	**If YES, To Whom?** Jim Amos-BLM Mike Bratcher-OCD	
By Whom? Production Assistant Leonard Aguilar	**Date and Hour** **10/08/15 7:00 pm**	
Was a Watercourse Reached? ☐ Yes ☒ No	**If YES, Volume Impacting the Watercourse** N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*
Water pump clogged and sent all production to the oil tank, the tank ran over. The lease operator shut in wells, switched tanks and drained heater.

Describe Area Affected and Cleanup Action Taken.*
200 BBL of oil was released all in containment and 185 BBL of oil recovered from containment. With an over spray of .5 BBL of oil that sprayed off pad onto the southwest corner a 20' X 50' area. An environmental company will be called out to evaluate the area.

As per approved work plan, the impacted soil inside the battery and the impacted area on the pad was loosened by use of hand tools. A liberal application of MicroBlaze solution was applied to the impacted area. Thirty days after the application, soil samples were collected from the same sample points as in the delineation and analyzed for TPH and BTEX. An additional soil sample was selected from a sample point in the pasture for confirmation. Lab analysis indicates a drastic reduction in contaminant levels. Loosening of the soil aided the remediation efforts by providing sufficient aeration and penetration of the MicroBlaze. The samples were analyzed by Cardinal Laboratories.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *Jeanette Barron*	**OIL CONSERVATION DIVISION**
Printed Name: **Jeanette Barron**	Approved by Environmental Specialist:
Title: **Field Admin Support**	Approval Date: 2/15/2016 — Expiration Date: N/A
E-mail Address: **Jeanette.barron@dvn.com**	Conditions of Approval: FINAL — Attached ☐
Date: 2/11/16 Phone: **575.748.1813**	

* Attach Additional Sheets If Necessary

2RP-3324