Form 3160-5
(March 2012)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB No. 1004-0137
Expires: October 31, 2014

5. Lease Serial No. NMNM 025 365

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE – *Other instructions on page 2.*

7. If Unit of CA/Agreement, Name and/or No.

1. Type of Well
☑ Oil Well ☐ Gas Well ☐ Other

8. Well Name and No. Neff 25 Federal #9H

2. Name of Operator OXY USA Inc. 16696

9. API Well No. 30-015-41459

3a. Address P.O. Box 50250 Midland, TX 79710

3b. Phone No. *(include area code)* 432-685-5717

10. Field and Pool or Exploratory Area Livingston Ridge Bone Spring

4. Location of Well *(Footage, Sec., T.,R.,M., or Survey Description)*
2160 FNL 150 FWL SWNW (E) Sec 25 T22S R31E

11. County or Parish, State Eddy NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☑ Subsequent Report	☐ Casing Repair	☐ New Construction	☐ Recomplete	☑ Other Completion
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	
☐ Final Abandonment Notice	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

RUPU 10/18/13, RIH & tag POST, drill out, push down to 11000', RIH w/ CBL. TIH, drill and clean out to PBTD @ 14504'. Pressure test csg to 8500#, lost 150# in 30min, but tested good. RIH & perf @ 14480-14130, 13955-13605, 13430-13080, 12905-12555, 12380-12030, 11855-11505, 11330-10980, 10805-10440' Total 216 holes. Frac in 8 stages w/ 83034g 15# Linear Gel + 24000g 15% HCl acid + 10061109g 15# XL-Borate + 176484g Treated Wtr w/ 1884720# sand, RD HES. RIH with 2-7/8" tbg & pkr & set 9100'. Flow to clean up and test well for potential.

Accepted for record
CRD NMOCD 1/15/2014

RECEIVED
JAN 15 2014
NMOCD ARTESIA

14. I hereby certify that the foregoing is true and correct. Name *(Printed/Typed)* David Stewart

Title Sr. Regulatory Advisor

Signature

Date 12/4/13

ACCEPTED FOR RECORD

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date JAN 11 2014

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)