Submit 3 Copies to Appropriate District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

C15F
DR

Form C-103
Revised 1-1-89

WELL API NO. 30-015-00693

5. Indicate Type of Lease STATE [X] FEE [ ]

6. State Oil & Gas Lease No. B 11538

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name: Delhi

1. Type of Well: OIL WELL [X] GAS WELL [ ] OTHER

2. Name of Operator: Pronghorn Mgt Corp.

8. Well No. 1

3. Address of Operator: P.O. Box 1777

9. Pool name or Wildcat: Empire Yates 7 Rivers

4. Well Location

Unit Letter A : 330 Feet From The North Line and 330 Feet From The East Line

Section 36 Township 17S Range 27E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3609GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	[ ]	PLUG AND ABANDON	[X]	REMEDIAL WORK	[ ]	ALTERING CASING	[ ]
TEMPORARILY ABANDON	[ ]	CHANGE PLANS	[ ]	COMMENCE DRILLING OPNS.	[ ]	PLUG AND ABANDONMENT	[ ]
PULL OR ALTER CASING	[ ]			CASING TEST AND CEMENT JOB	[ ]		
OTHER:	[ ]			OTHER:	[ ]		

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in and rig up unit.
2. Tag for total depth → set 100' plug 402' to 502' (Tag)
   → Perf csg. squeeze 100' of cmt outside csg 300' to 400'
   → set 100' plug 300' to 400'
3. ~~Cement well from total depth to surface~~
   → Perf csg. squeeze 100' of cmt outside of csg 150' to 250'
   → set 100' plug - 150' to 250'
4. Erect dry hole marker → Perf csg - squeeze 60' of cmt outside csg 50'-100'
5. Clean location. → 60' surface plug

SEP 2001
RECEIVED
OCD - ARTESIA

Salt gel mud consisting of 10#
Brine W/25# of gel per bbl
must be placed between each plug

Notify OCD 24 hrs. prior to any work done

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [signature] TITLE Partner DATE 9/14/01

TYPE OR PRINT NAME Geo A. Baber TELEPHONE NO. 393-9176

(This space for State Use)

APPROVED BY [signature] TITLE Field Rep II DATE 9-27-01

CONDITIONS OF APPROVAL, IF ANY: