Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED
APR 26 1977
O. C. C.
ARTESIA, OFFICE

Form approved,
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
SF/LC-063578

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal

9. WELL NO.
2-34

10. FIELD AND POOL, OR WILDCAT
Red Lake Queen Grayburg East

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 34, T-16S, R-28E, NMPM

1.
OIL WELL [X] GAS WELL [ ] OTHER

2. NAME OF OPERATOR
Southern Union Production Company

3. ADDRESS OF OPERATOR
Suite 1700, 8350 N Central Expressway, Dallas, Texas 75206

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
990' FNL & 2310' FWL

14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE
	3853 GL	Eddy	New Mexico

16. **Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	PULL OR ALTER CASING	
FRACTURE TREAT	MULTIPLE COMPLETE	
SHOOT OR ACIDIZE	ABANDON*	X
REPAIR WELL	CHANGE PLANS	
(Other)		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREATMENT	ALTERING CASING	
SHOOTING OR ACIDIZING	ABANDONMENT*	
(Other)		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

We intend to plug and abandon this well as follows:
1. A cement plug will be set across the perforations in the producing zone (Top 1418'; Bottom 1468').
2. A cement plug will be set at the surface and a dry hole marker installed.
3. Surface equipment will be removed and the location will be cleaned-up.

RECEIVED
SEP 13 1976
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED _Dan R. Collier_   TITLE: Operations Asst.   DATE 9/10/76

(This space for Federal or State office use)

APPROVED BY _____   TITLE: _____   DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side