Form 9-331
(May 1963)

UNITED STATES NM OIL CONS MISSION
DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)
GEOLOGICAL SURVEY Artesia, NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
   LC
   71-063934

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1.
OIL WELL [X]   GAS WELL [ ]   OTHER

O. C. D.
ARTESIA, OFFICE
MAY 16 1984

2. NAME OF OPERATOR
AMCO Production Co.

3. ADDRESS OF OPERATOR
P.O. Box 727, Artesia, New Mex. 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

2310' FNL-330' FWL - 13-16-30

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
   ETZ Fed.

9. WELL NO.
   1

10. FIELD AND POOL, OR WILDCAT
    Henshaw, Q.G.S.A.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
    13-16-30

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

12. COUNTY OR PARISH Eddy
13. STATE N. MEX

16.
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF [ ]	PULL OR ALTER CASING [ ]
FRACTURE TREAT [ ]	MULTIPLE COMPLETE [ ]
SHOOT OR ACIDIZE [ ]	ABANDON* [ ]
REPAIR WELL [ ]	CHANGE PLANS [ ]
(Other)	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF [ ]	REPAIRING WELL [X]
FRACTURE TREATMENT [ ]	ALTERING CASING [ ]
SHOOTING OR ACIDIZING [ ]	ABANDONMENT* [ ]
(Other) Run Casing	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

2-13-84
Rig up and pull on 7" casing. Stuck in bottom, would not come.
Run 6¼" bit on drill stem.

2-14-84
Clean out to 3200', Circulate hole 5 hrs. Run 3200' 4½",10.5# casing
with insert float. Cement with 85 sacks, class C.

2-15-84
Run temperature survey. Cement top at 2910'.

2-20-84
Log well and perforate casing,3160 to 3130 with 26 holes (1 per. ft.)

2-21-84
Run tubing with tention packer. Spot acid on perfs. Break down with
1250 gals. 15% acid. Start swabing back.

18. I hereby certify that the foregoing is true and correct

SIGNED _J.B. Adamson_   TITLE _Owner-Operator_   DATE _3-5-84_

ACCEPTED FOR RECORD
(This space for Federal or State office use)

APPROVED BY _HWD_   TITLE _____   DATE _____
CONDITIONS OF APPROVAL, IF ANY   MAY 16 1984

Carlsbad   NEW MEXICO *See Instructions on Reverse Side