September 16, 1965

Ryder Scott Management Company
922 8th Street
Wichita Falls, Texas

Re. H. J. Loe Federal #4 H,
25-16S-30E, Square Lake
Pool, Eddy County, N.M.

Gentlemen:

Enclosed please find your Form C-104 for the above-mentioned well. Please show the perforations, P.B.T.D. and casing shoe. In Section V you show actual production 40 barrels during the test, in the break down 20 barrels of oil and a trace of water. It appears an error has been made.

Further, since this well was drilled with Rotary tools, it will be necessary for you to submit three (3) notarized tabulation of Deviation Surveys.

Very truly yours,

OIL CONSERVATION COMMISSION

M. L. Armstrong
Supervisor, District No. II

MLA/bh

[illegible]

[illegible] Department [illegible]
[illegible]
[illegible]

[illegible] Dr. [illegible] Lue Foreman [illegible]
[illegible] Department [illegible]
[illegible] Dallas [illegible]

Dear Lue:

[illegible] I have filed your [illegible] form [illegible] for the [illegible] [illegible] [illegible]