Crow Flat 29 Federal Com #2, 30-015-31760, NM-54856

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
MorrowCarbonat	9176'	9282'	
Morrow Clastics	9282'	9572'	
Barnett Shale	9572'	9620'	
Chester Lime	9620'	9752'	
Miss Lime	9752'	9800'	

DEPTH	ACID, SHOT, FRACTURE, CEMEMNT SQUEEZE, ETC.. (continued from the front)

38. GEOLOGIC MARKERS

NAME	TOP MEAS. DEPTH	TOP TRUE VERT. DEPTH
Yates	315'	
Bowers	854'	
Queen	1030'	
San Andres	1830'	
Glorieta	3272'	
Tubb Sand	4584'	
Abo Shale	5294'	
Wolfcamp	6536'	
Cisco	7918'	
Canyon	8222'	
Strawn	8756'	
Atoka	8916'	
Atoka Shale	9075'	
MorrowCarbonate	9176'	
MorrowClastics	9282'	
Barnett Shale	9572'	
Chester Lime	9620'	
Miss Lime	9752'	
Total Depth	9800'	