ARTESIA OFFICE COPY NMOCC COPY copy to SF

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

# SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED
MAY 13 1977
O. C. C.

1. OIL WELL [X] GAS WELL [ ] OTHER

2. NAME OF OPERATOR: Skelly Oil Company

3. ADDRESS OF OPERATOR: P. O. Box 1351, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface: Unit Letter C, 765' FNL & 2058' FWL Sec. 22-17S-31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.): 3850' DF

5. LEASE DESIGNATION AND SERIAL NO.: LC-029419(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME: - - - -

7. UNIT AGREEMENT NAME: Skelly Unit

8. FARM OR LEASE NAME: Skelly Unit

9. WELL NO.: 43

10. FIELD AND POOL, OR WILDCAT: Grayburg-Jackson

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA: Sec. 22-17S-31E

12. COUNTY OR PARISH: Eddy

13. STATE: New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO: | | | | SUBSEQUENT REPORT OF: | | | |
|---|---|---|---|---|---|---|---|
| TEST WATER SHUT-OFF | [ ] | PULL OR ALTER CASING | [ ] | WATER SHUT-OFF | [ ] | REPAIRING WELL | [ ] |
| FRACTURE TREAT | [ ] | MULTIPLE COMPLETE | [ ] | FRACTURE TREATMENT | [ ] | ALTERING CASING | [ ] |
| SHOOT OR ACIDIZE | [ ] | ABANDON* | [ ] | SHOOTING OR ACIDIZING | [ ] | ABANDONMENT* | [ ] |
| REPAIR WELL | [ ] | CHANGE PLANS | [ ] | (Other) | | | |
| (Other) Acid-Frac perfs. 3128-3748' | | | [X] | (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) | | | |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1) Move in workover rig. Pull rods and tubing.
2) Treat perfs. 3721-3748' with 2400 gals. gelled pad and 2000 gals. acid. Flush with 40 bbls. treated water.
3) Isolate perfs. 3451-3461' and treat with 2400 gals. gelled pad and 2000 gals. acid. Flush with 40 bbls. treated water.
4) Isolate perfs. 3334-3373' and treat with 1100 gals. gelled acid pad and 1000 gals. acid. Flush with 40 bbls. treated water.
5) Isolate perfs. 3128-3298' and treat with 2800 gals. gelled pad and 2500 gals. acid. Flush with 40 bbls. treated water.
6) Return well to producing status pumping Grayburg-Jackson perfs. 3128-3748'.

RECEIVED
FEB - 6 1976
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

NIT cancelled
5-12-77
RB

18. I hereby certify that the foregoing is true and correct

SIGNED D. R. Crow TITLE Lead Clerk DATE 2-4-76

(This space for Federal or State office use)

APPROVED BY TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

(noted) D. W. GORDON

FEB 1976
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

*See Instructions on Reverse Side