37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Rustler	555	735	
Salado	735	1700	
Tansill	1700	1855	
Yates	1855	2174	
Seven Rivers	2174	2792	
Queen Sand (Artesia)	2792	2822	
Grayburg	3208	3552	
San Andres	3552	4335 (TD)	

DEPTH	ACID, SHOT, FRACTURE, CEMEMNT SQUEEZE, ETC.. (continued from the front)
	+ 16,000# resin coated sand.
3824'-3941'	Acidized w/2500 gals 15% HCl acid.
3671'-3677'	Acidized w/1075 gals 15% HCl acid. Acid-frac'd w/12,700 gals of WR-135 gel + 12,000 gals 15% HCl acid. Frac'd w/13,000 gals x-linked 30# gelled fluid + 24,000# 20/40 Brady sand + 6000# resin coated sand..
3485'-3535'	Acidized w/1100 gals 15% HCl acid. Cmt squeezed w/75 sxs cmt.
3516'-3535'	Acidized w/500 gals 15% HCl acid.
3485'-3510'	Acidized w/1100 gals 15% HCL acid.
3297'-3458'	Acidized w/1675 gals 15% HCl acid.
3277'-3535'	Frac'd w/42,000 gals Vik I-30 gel + 101,000# 20/40 Brady sand + 31,000# resin coated sand.

38. GEOLOGIC MARKERS

NAME	TOP MEAS. DEPTH	TOP TRUE VERT. DEPTH