H. E. West "B" #81, 30-015-28316, LC-029426-B

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Rustler	460	610	
Salado	610	1604	
Tansill	1604	1762	
Yates	1762	2076	
Seven Rivers	2076	2692	
Queen (Artesia)	2692	3134	
Grayburg	3134	3439	
San Andres	3439	3880 (TD)	

DEPTH	ACID, SHOT, FRACTURE, CEMEMNT SQUEEZE, ETC.. (continued from the front)

38. GEOLOGIC MARKERS

NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH