FOLD

PLUGS AND ADAPTERS

Heaving plug—Material .... Length .... Depth set ....

Adapters—Material .... Size ....

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
		Nitro-Glycerin	150qts	9/12	2645-2675	3150
		Nitro-Glycerin	160qts	9/15	3056-3098	3150

TOOLS USED

Rotary tools were used from .... feet to .... feet, and from .... feet to .... feet

Cable tools were used from 0 feet to 3157 feet, and from .... feet to .... feet

DATES

...................................., 19...... Put to producing September 15, 1940

The production for the first 24 hours was 45 barrels of fluid of which 100 % was oil; 0 % emulsion; 0 % water; and 0 % sediment. Gravity, °Bé. ....

If gas well, cu. ft. per 24 hours .... Gallons gasoline per 1,000 cu. ft. of gas ....

Rock pressure, lbs. per sq. in. ....

EMPLOYEES

L. D. Coleman, Driller E. L. Atwood, Driller

Darle Beasley, Driller Roy R. Burkhart, Driller

FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
0	170	170	Sand, Gyp, & RI red Clay
170	250	80	Red Bed & Sand (Water)
250	261	11	Red Bed
261	273	12	Shale Brown
273	282	9	Sand
282	350	68	Shale Red
350	360	10	Salt & Anhydrite
360	475	115	Salt & Potash
475	520	45	Salt & Anhydrite
520	575	55	Salt & Shale
575	625	50	Salt & Potash
625	675	50	Salt & Anhydrite
675	730	55	Salt & Shale
730	940	210	Anhydrite
940	965	25	Shale
965	975	10	Anhydrite
975	1015	40	Anhydrite & Shale
1015	1050	35	Anhydrite
1050	1125	75	Anhydrite & Shale
1125	1330	205	Anhydrite
1330	1340	10	Lime
1340	1475	135	Lime & Anhydrite
1475	1640	165	Anhydrite
1640	1675	35	Shale & Anhydrite
1675	1785	110	Anhydrite

(OVER)