Form 3160-5
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Artesia, NM 88210

Form Approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
NM 02426 c/SF

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED
APR 06 1983
O. C. D.
ARTESIA, NEW MEXICO 88210

1. OIL WELL ☐ GAS WELL ☐ OTHER WIW - TA

7. UNIT AGREEMENT NAME
W.L.H.U. GRB #4 SD UT

2. NAME OF OPERATOR
NEWMONT OIL COMPANY ✓

8. FARM OR LEASE NAME
Tract 19B

3. ADDRESS OF OPERATOR
P.O. BOX 1305 ARTESIA, NEW MEXICO 88210

9. WELL NO.
4

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface
2310' FNL 2310' FEL Sec. 9-18-29

10. FIELD AND POOL, OR WILDCAT
LOCO HILLS (Q.G.SA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 9-18-29

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3480'

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexic

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐	WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐	FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐	SHOOTING OR ACIDIZING	☐	ABANDONMENT*	XX
REPAIR WELL	☐	CHANGE PLANS	☐	(Other)			
(Other)				(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was plugged and abandon as follows:

12/7/82....Spotted 50 sacks cement at 2241'. WOC.

12/8/82....Tagged plug at 2281'. Spotted 25 sacks cement @ 2281'. Csg leak between 280' and 404'. Perf base of salt @ 785' and squeezed w/50 sacks cement. WOC.

12/14/82...Tagged plug at 212'. Set 15 sack at surface and dry hole marker.

Location ready for inspection

RECEIVED
MAR 30 1983
OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Lonnie J. Wingfield TITLE Area Manager DATE 3/28/83

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Post FD-2
4-15-83
P+A

*See Instructions on Reverse Side