Form 9-331
(May 1963)

U.. ..ED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

9sF

SUBMIT IN T.. .ICATE:
(Other Instruc.. ..on re..

N OIL CONS.. COMMISSION
Drawer DD

5. LEASE DESIGNATION AND SERIAL NO.
LC-0584 81

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED BY

NOV 14 1983

O. C. D.
ARTESIA, OFFICE

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
West Loco Hills Grp #4

1. OIL WELL ☐   GAS WELL ☐   OTHER   WIW – T.A.

2. NAME OF OPERATOR
Newmont Oil Company ✓

8. FARM OR LEASE NAME   SD U
Tract 11 B

3. ADDRESS OF OPERATOR
P. O. Box 1305 Artesia, New Mexico 88210

9. WELL NO.
9

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FSL & 660' FWL of Sec. 11, 18S-29E:

10. FIELD AND POOL, OR WILDCAT
Loco Hills (Q.G. SA).

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 11-18S-29E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3509' GL

12. COUNTY OR PARISH
Eddy

13. STATE

16.
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐	WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐	FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐	SHOOTING OR ACIDIZING	☐	ABANDONMENT*	XX
REPAIR WELL	☐	CHANGE PLANS	☐	(Other) _____			
(Other)							

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5/1/83..Spotted 50 sks cmt w/2% CalCl ....WOC.   Tagged plug at 2245'.   Perf
         and squeezed 50 sks of cement at 1000'.

5/3/83...Tagged plug at 885', perf at 400'.   Squeezed 50 sks cmt. WOC.
         Tagged plug at 290'.   Set 15 sk cmt plug and dry hole marker.

         Location ready for inspection

BUREAU OF LAND MANAGEMENT
RECEIVED
JUL 21 1983
DIST. 6 N. M.
ROSWELL, NEW MEXICO

Post JD 2
11-18-83
P4A

18. I hereby certify that the foregoing is true and correct.

SIGNED _Ernest J. McKenzie_   TITLE ___Area Manager___   DATE __7/20/83__

(This space for Federal or State office use)

APPROVED BY _____   TITLE _____   DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side