Parker Deep 5 Fed Com #2

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Grayburg	3471	3477	Drlg Break - Oil Show
			No Cores
			No DST's

38. GEOLOGIC MARKERS

NAME	TOP MEASURED DEPTH	TOP TRUE V.D.
Rustler	475	
Yates	1900	
7 Rivers	2200	
Queen	2870	
Grayburg	3215	
San Andres	3800	
B.S.	5280	
Wolfcamp	8860	
Penn Shale	9920	
Strawn	10750	
Atoka	11010	
Morrow	11360	
MW Clastics	11505	
U. Miss.	11845	

RECEIVED
2001 JUN 11 AM 8:55
BUREAU OF LAND MGMT.
ROSWELL OFFICE