FOLD

PLUGS AND ADAPTERS

Heaving plug—Material ..... Length ..... Depth set .....

Adapters—Material ..... Size .....

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
Not shot or initiated						

TOOLS USED

Rotary tools were used from ..... feet to ..... feet, and from ..... feet to ..... feet

Cable tools were used from 0 feet to 3595 feet, and from ..... feet to ..... feet

DATES

..... , 19..... Put to producing ..... , 19.....

The production for the first 24 hours was ..... barrels of fluid of which ..... % was oil; ..... % emulsion; ..... % water; and ..... % sediment. Gravity, °Bé. .....

If gas well, cu. ft. per 24 hours ..... Gallons gasoline per 1,000 cu. ft. of gas .....

Rock pressure, lbs. per sq. in. .....

EMPLOYEES

..... G. E. Barker ....., Driller ..... , Driller

..... G. P. Miller ....., Driller ..... , Driller

FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
0	100	100	Sand and gravel
100	385	285	Red Beds
385	490	105	Red Beds, Sand (Water at 490')
490	915	425	Red Beds
915	935	20	Anhydrite
935	948	13	Red Beds
948	1015	67	Anhydrite
1015	1105	90	Anhydrite and Salt
1105	1200	95	Salt
1200	1240	40	Anhydrite
1240	1270	130	Salt
1270	1435	165	Anhydrite
1435	1445	10	Anhydrite and Sand (Water)
1445	1975	530	Anhydrite
1975	2000	25	Anhydrite and Lime
2000	2195	195	Anhydrite
2195	2305	110	Anhydrite and Lime
2305	2345	40	Anhydrite
2345	2380	35	Anhydrite and Lime Shells
2380	2415	35	Anhydrite
[illegible]	[illegible]	[illegible]	Lime
[illegible]	[illegible]	[illegible]	Lime and Anhydrite
[illegible]	[illegible]	[illegible]	Lime
[illegible]	[illegible]	[illegible]	Lime and Anhydrite
[illegible]	[illegible]	[illegible]	Lime, Anhydrite, and Shale
[illegible]	3595	[illegible]	

(over)

15—[illegible]

FORMATION RECORD—Continued