C/SF

Form 3160-5
(November 1983)
(Formerly 9-331)

NM OIL CONS. COMMISSION
Drawer DD
Artesia, NM 88210

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE* (Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.: NM 2537

6. IF INDIAN, ALLOTTEE OR TRIBE NAME:

7. UNIT AGREEMENT NAME:

8. FARM OR LEASE NAME: South Taylor 13 Federal

9. WELL NO.: 1

10. FIELD AND POOL, OR WILDCAT: Undesignated Grayburg

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA: Sec. 13, T18S, R31E

12. COUNTY OR PARISH: Eddy

13. STATE: NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED
JUN 15 '88
O. C. D.
ARTESIA, OFFICE

1. OIL WELL [X] GAS WELL [ ] OTHER

2. NAME OF OPERATOR: Harvey E. Yates Company

3. ADDRESS OF OPERATOR: P.O. Box 1933, Roswell, New Mexico 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface: 330' FSL & 990' FEL Unit Letter P

14. PERMIT NO.: API 30-015-25594

15. ELEVATIONS (Show whether DF, RT, GR, etc.): 3716 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	[ ]	PULL OR ALTER CASING	[ ]	WATER SHUT-OFF	[ ]	REPAIRING WELL	[ ]
FRACTURE TREAT	[ ]	MULTIPLE COMPLETE	[ ]	FRACTURE TREATMENT	[✓]	ALTERING CASING	[ ]
SHOOT OR ACIDIZE	[ ]	ABANDON*	[ ]	SHOOTING OR ACIDIZING	[✓]	ABANDONMENT*	[ ]
REPAIR WELL	[ ]	CHANGE PLANS	[ ]	(Other) PB to Grayburg			
(Other)				(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-20-88 Perf 4312-4410' (1 JSPF - 6 holes)
5-21-88 CIBP set @ 5000'. Acidize w/1200 gals 15% HCL
5-24-88 Frac 4312-4410 (OA) w/40,000 gals WF 40 & 60,000 16/30 Ottawa.
5-25-88 GIH w/SN, tbg, anchor. Anchor @ 4186', SN @ 4507'.
5-26-88 Hang well on, turn over to pumper.

RECEIVED
MAY 27 | 27 PM '88
CARLSBAD, NEW MEXICO
AREA MANAGERS

skh

18. I hereby certify that the foregoing is true and correct

SIGNED [signature] TITLE Production Manager/Engineer DATE 5-26-88

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUN [illegible] 1988

SJS

CARLSBAD, NEW MEXICO

*See Instructions on Reverse Side