Submit 3 Copies to Appropriate District Office

State of New Mexico

Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-015-20319

5. Indicate Type of Lease STATE [X] FEE [ ]

6. State Oil & Gas Lease No.
LG 2724

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED
APR 01 1997
OIL CON. DIV.
DIST. 2

7. Lease Name or Unit Agreement Name
Featherstone State

1. Type of Well: OIL WELL [XX] GAS WELL [ ] OTHER

2. Name of Operator
Southwest Royalties, Inc.

8. Well No.
2

3. Address of Operator
P. O. Box 11390 Midland, TX 79702

9. Pool name or Wildcat
Millman - Grayburg

4. Well Location
Unit Letter 0 : 2310 Feet From The East Line and 990 Feet From The South Line

Section 18 Township 19S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3517 GL.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	[ ]	PLUG AND ABANDON	[ ]	REMEDIAL WORK	[ ]	ALTERING CASING	[ ]
TEMPORARILY ABANDON	[ ]	CHANGE PLANS	[ ]	COMMENCE DRILLING OPNS.	[ ]	PLUG AND ABANDONMENT	[X]
PULL OR ALTER CASING	[ ]			CASING TEST AND CEMENT JOB	[ ]		
OTHER:	[ ]			OTHER:			[ ]

12. Describe Proposed or Completed Operations (*Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work*) SEE RULE 1103.

3-3-97 - MIRU, nipple down wellhead, run in hole with tubing load hole w/mud laiden fluid. Pumped plug #1, 30 sxs at 1800'. WOC and tagged plug #1 1607'. Laid down Tbg. and shut well in for the day.

3-4-97 - Open well, 0 psi. Run Tbg. to 1200' and pumped plug #2, 25 sxs at 1200'. WOC and tagged plug #2 at 1137' w/wireline. Perf csg. at 450', ran in hole with packer and sqz plug #3, 50 sxs, circulated cement to surface, no tag needed. Dug out cellar, cut off wellhead and spotted 15 sx surface plug 10' to surface. Set dry hole marker, cut off dead-men, covered pit, leveled and cleaned location. Job complete.

Post ID-2
5-13-97
P&A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James Blount TITLE AREA SUPERVISOR DATE 3-27-97

TYPE OR PRINT NAME JAMES BLOUNT TELEPHONE NO. 915-686 9427

(This space for State Use)

APPROVED BY [signature] TITLE Field Rep DATE 7/14/98

CONDITIONS OF APPROVAL, IF ANY: