

STRAWBERRY "7" FED. #2
Located at 1300' FNL and 1750' FEL
Section 7, Township 19 South, Range 31 East,
N.M.P.M., Eddy County, New Mexico.

basin surveys
focused on excellence in the oilfield
P.O. Box 1786
1120 N. West County Rd.
Hobbs, New Mexico 88241
(505) 393-7316 - Office
(505) 392-3074 - Fax
basinsurveys.com

W.O. Number: 2416AA - KJG CD#4
Survey Date: 04-08-2002
Scale: 1" = 2000'
Date: 04-09-2002

DEVON SFS OPERATING, INC.