Form 3160-5
(November 1983)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE (Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
NM-02918

RECEIVED BY
MAY 07 1985
O. C. D.
ARTESIA, OFFICE

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER

85 MAY -2 AM 9 03

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
N/A

7. UNIT AGREEMENT NAME
N/A

2. NAME OF OPERATOR
CASA PETROLEUM, INC. ✓

8. FARM OR LEASE NAME
WEST [illegible] FEDERAL

3. ADDRESS OF OPERATOR
105 NORTH SEVEN STREET ARTESIA, NEW MEXICO 88210

9. WELL NO.
1

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
660' FNL & 660' FEL of Section 8
(UNIT A)
(NE/4 NE/4)

10. FIELD AND POOL, OR WILDCAT
[illegible]

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
SEC. 8, T-19-S, R-32-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3960 GL

12. COUNTY OR PARISH
EDDY

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO: | | | | SUBSEQUENT REPORT OF: | | | |
|---|---|---|---|---|---|---|---|
| TEST WATER SHUT-OFF | ☐ | PULL OR ALTER CASING | ☐ | WATER SHUT-OFF | ☐ | REPAIRING WELL | ☐ |
| FRACTURE TREAT | ☐ | MULTIPLE COMPLETE | ☐ | FRACTURE TREATMENT | ☐ | ALTERING CASING | ☐ |
| SHOOT OR ACIDIZE | ☐ | ABANDON* | X | SHOOTING OR ACIDIZING | ☐ | ABANDONMENT* | ☐ |
| REPAIR WELL | ☐ | CHANGE PLANS | ☐ | (Other) | | | |
| (Other) | | | | (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) | | | |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PLAN TO PLUG WELL AS FOLLOWS:

SET CAST IRON BRIDGE PLUG @ 6250' SHUT OFF BONE SPRINGS
CEMENT WITH 10 SKS ON TOP
SET CAST IRON BRIDGE PLUG @ 4550' SHUT OFF DELAWARE
CEMENT WITH 15 SKS ON TOP
SET CAST IRON BRIDGE PLUG @ 3000' SHUT OFF DELAWARE
CEMENT WITH 15 SKS ON TOP
SET CAST IRON BRIDGE PLUG @ 2000' SHUT OFF YESO
CEMENT WITH 15 SKS ON TOP
SET 10 SACK PLUG AT SURFACE
SET DRY HOLE MARKER
CLEAN LOCATION.

18. I hereby certify that the foregoing is true and correct

SIGNED Mary A. Kaiser TITLE Secretary DATE 4/30/85

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the