Form 9–331
(May 1963)

N. M. ___ ___ ___

_lap. __ __ 14_

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN T___ ___ICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42–R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 1128

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECE___

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

–

1.

OIL WELL ☐   GAS WELL ☐   OTHER   Dry Hole

7. UNIT AGREEMENT NAME

–

2. NAME OF OPERATOR

C & K Petroleum, Inc.

___ ___ 1974

8. FARM OR LEASE NAME

Morrison Federal

3. ADDRESS OF OPERATOR

607 Midland National Bank Bldg., Midland, Texas 79701

9. WELL NO.

1

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FN and 1980' FE Lines, Sec. 26, T-26-S, R-23-E,
Eddy County, New Mexico.

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 26, T-26-S, R-23-E

14. PERMIT NO.

30-015-21061

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4110 Gr.

12. COUNTY OR PARISH   Eddy

13. STATE   N. M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other)	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) _Plug and Abandon_	☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Dowell, Hobbs, N. M., Rigged Up Feb. 25, 1974 and Plugged Well as follows:

Plug #1 From 8800' to 8700' with 40 sx. Cement.
Plug #2 From 7800' to 7700' with 40 sx. Cement.
Plug #3 From 6250' to 6150' with 40 sx. Cement.
Plug #4 From 4847' to 4747' with 40 sx. Cement.
Plug #5 From 3300' to 3200' with 40 sx. Cement.
Plug #6 From 1930' to 1830' with 40 sx. Cement.
Plug #7 (Surface Plug) 15 sx.

RECEIVED

MAR 28 1974

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

1. Install Dry Hole Marker.
2. Clean and Level Location.
3. Note: This plugging procedure approved by. Mr. Jim Knauf, February 25, 1974.

18. I hereby certify that the foregoing is true and correct

SIGNED _____   TITLE Administrative Supervisor   DATE March 27, 1974

(This space for Federal or State office use)

APPROVED BY _____   TITLE _____   DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side