SOUTHWESTERN DIVISION SPILL REPORT FORM

DATE OF LEAK 2-9-92
FIELD BRUSHY DRAW
LEASE SOSA FEDERAL
COUNTY EDDY
STATE NEW MEXICO

SECTION 15
BLOCK
SURVEY
TOWNSHIP 26 S
RANGE 29 E

CAPS BATTERY 6887
MCOT # N/A

LANDOWNER NAME BLM
LANDOWNER NOTIFIED? (YES)

	SPILLED	RECOVERED
VOLUME OF OIL	2 BBLS	0 BBLS
VOLUME OF WATER	N/A	N/A
VOLUME OF CHEMICAL	N/A	N/A
IF CHEMICAL, NAME		

TYPE OF SURFACE AFFECTED
LAND X
WATER
DRY DRAINAGE
(IF WATER OR DRAINAGE, NAME IF KNOWN)

AGENCY NAME	PERSON CONTACTED	TIME	DATE
BLM CARLSBAD 887-6544	JIM AMOS	8:00 AM	2-3-92

DESCRIPTION OF SPILL

GENERAL SPILL LOCATION
INJ. WELL#
PROD. WELL# X
FLOWLINE X
T/B OR S/B
SWD
PIT
INJECTION LINE
PLANT
DRLG RIG
OTHER
LINE #

SPECIFIC SPILL LOCATION
VESSEL
CONNECTION
CHEMICAL SYSTEM
DISCHARGE LINE
FILL LINE
MANIFOLD
PIPING X
TUBING
WELLHEAD
VALVES
TANK
PUMP
OTHER

CAUSE OF LEAK
ALARM FAILURE
CRACK/BREAK
PACKING
EXT. CORROSION X
INT. CORROSION
EXTERNAL DAMAGE
FREEZING
HUMAN ERROR
PLUGGED
POWER FAILURE
VANDALISM
OTHER

TYPE OF MATERIAL
ALUMINUM BRONZE/ BRASS
CMT LINED STEEL
FIBERGLASS
STEEL X
TRANSITE
PLASTIC PIPE
STAINLESS STEEL
EXT. COATED
INT. COATED
SIZE
EST. AGE

LEAK SITE DESCRIPTION
ABOVE GROUND
BELOW GROUND X
WELD
TOP
BOTTOM

COSTS
REPAIRS	250.00
CLEAN UP	150.00
OIL LOSS	30.00
CHEMICAL LOSS	N/A

ACTIONS TAKEN/COMMENTS: (If HAZWOPER incident, attach a separate sheet documenting steps taken)
REPLACE FLOWLINE JOINTS UNDER CALACHE PAD. DOPE + WRAP TO PREVENT CORROSION

3379
82848

DRAWING (Include well number for reference)

E. Nwambuonwo
UPA
claims / row
SOSA FED
K. Coleman
WELL #2



SPILL AREA ON PAD.
CALACHE STAINED AREA
3FT x 30 FT

REPORTED BY ED CELLARS TITLE BEAT PUMPER DATE 2-9-92
FIELD SUPERVISOR'S SIGNATURE

- FAX COPY OF REPORT TO OP. SUPT IF POTENTIAL NRC/BLM REPORT
- SEND COMPLETED FORM TO SALLY URBY, REGULATORY AFFAIRS, #3 PC, MIDLAND