37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Delaware Mtn. Group	4534'	8380'	SAND, SHALE + LIME

38. GEOLOGIC MARKERS

NAME	TOP MEAS. DEPTH	TOP TRUE VERT. DEPTH
Rustler Anhydrite	761'	761
SALT	1093'	1093'
BASE SALT	4308'	4308'
Delaware Mtn. Group	4320'	4320'
Bone Spring Lime	8188'	8188'