Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 078344

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1.

OIL WELL ☒   GAS WELL ☐   OTHER

7. UNIT AGREEMENT NAME

East Bisti Unit

2. NAME OF OPERATOR

Shelly Oil Company

8. FARM OR LEASE NAME

3. ADDRESS OF OPERATOR

1860 Lincoln Street, Denver, Colorado   80203

9. WELL NO.

73

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

530' FSL and 2110' FEL Section 35-25N-10W

10. FIELD AND POOL, OR WILDCAT

Bisti Lower Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 35-25N-10W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6749' GR   6761' KB

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other)

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) _____

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

All depths shown are from ground level.
6-26-71 - MI & RU Aztec Well Service Unit.
Pulled rods. Spotted cement plug from 5418' to 5318'. Pulled 2" tubing,
worked 5-1/2" casing. Rigged up blue jet, perforated from 1730' - 1731' w/4 shots.
Ran 2" tubing, spotted cement plug from 1731' to 1581'. Pulled 2" tubing, shot 5-1/2"
casing off at 1025'. Spotted cement plug from 1098' to 900', 73' inside and 125' above 5-
1/2" casing stub. Total 5-1/2" casing pulled 32 joints 1029'.
Spotted 10' cement plug in surface casing. Installed dry hole marker.
Completed P & A 7-1-71.

18. I hereby certify that the foregoing is true and correct

SIGNED _____   TITLE   Lead Clerk   DATE _____

(This space for Federal or State office use)

APPROVED BY _____   TITLE _____   DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side