Form 3160-5
(June 1990)

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
SF 078106

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE

7. If Unit or CA, Agreement Designation

1. Type of Well [X] Oil Well [ ] Gas Well [ ] Other P & A	8. Well Name and No. Gallegos #2
2. Name of Operator Dugan Production Corp.	9. API Well No. 30-045-87251
3. Address and Telephone No. P.O. Box 420, Farmington, NM 87499 (505) 325-1821	10. Field and Pool, or Exploratory Area Simpson Gallup
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FNL & 660' FWL, Sec. 22, T28N, R12W, NMPM	11. County or Parish, State San Juan, NM

12.   **CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION	
[ ] Notice of Intent	[X] Abandonment	[ ] Change of Plans
	[ ] Recompletion	[ ] New Construction
[X] Subsequent Report	[ ] Plugging Back	[ ] Non-Routine Fracturing
	[ ] Casing Repair	[ ] Water Shut-Off
[ ] Final Abandonment Notice	[ ] Altering Casing	[ ] Conversion to Injection
	[ ] Other _____	[ ] Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Spot 30 cu. ft. Class B + 3% CaCl2 plug at 5090.
2. Pulled tubing to 3810' and waited 3 hrs. to tag plug.
3. Unable to move tubing to tag plug.
4. Found hole in tubing at 1820'. Appears that portion of lower plug cement went out hole and stuck tubing in place.
5. Discussed options with Steve Mason of BLM. Received verbal approval to continue plug by leaving tubing in place and filling hole to surface with cement.
6. Pumped 173 cu. ft. Class B + 6% gel down tubing and circulated to surface.
7. Pumped 78 cu. ft. Class B 6% gel down 4½ - 8-5/8" annulus.
8. Plug complete 2-21-92. Operations witnessed by Kevin Schneider of BLM.

14. I hereby certify that the foregoing is true and correct

Signed _John Alexander_   Title __Operations Manager__

APPROVED
Date __2-25-92__

(This space for Federal or State office use)

Approved by _____   Title _____   FEB 27 1992
Conditions of approval, if any: Date _____

AREA MANAGER

*See Instruction on Reverse Side