A - PLUS WELL SERVICE, INC.

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211

COPY

Oil Conservation Division
State of New Mexico
1000 Rio Brazos Road
Aztec, NM 87410

July 16, 2001

Invoice #2439
Three States Navajo #1

1

Rig #4

For plugging and abandonment of the **Three States Navajo #1** well, which is located in Unit I, Section 27, T31N, R17W, San Juan County, NM.
This work was done under **Contract Number 01-521-25-212**.

Cost Summary:

Rig Cost - Pulling Unit (All Contractor fees for providing rig

5-31-01	Supervisor - 1/3 day	0.33	$380.00	$125.40
	Welder	1.50	$50.00	$75.00
6-20-01	Package Rig	3.0	$188.00	$564.00
	Supervisor	0.50	$380.00	$190.00
6-21-01	Package Rig	11.0	$188.00	$2,068.00
	Supervisor - 1 Day	1.0	$380.00	$380.00
	Crew Travel	1.0	$112.00	$112.00
	2-7/8" stripping rubber	1.0	$75.00	$75.00
6-22-01	Package Rig	10.0	$188.00	$1,880.00
	Supervisor - 1 Day	1.0	$380.00	$380.00
	Crew Travel	1.0	$112.00	$112.00
	2-7/8" stripping rubber	1.0	$75.00	$75.00
6-25-01	Package Rig	13.0	$188.00	$2,444.00
	Supervisor - 1 Day	1.0	$380.00	$380.00
	Crew Travel	1.0	$112.00	$112.00
	1 - 2-7/8" stripping rubber	1.0	$75.00	$75.00
6-26-01	Rig	10.0	$174.00	$1,740.00
	Supervisor - 1 Day	1.0	$380.00	$380.00
	Crew Travel	1.0	$112.00	$112.00
6-27-01	Rig	10.5	$174.00	$1,827.00
	Supervisor - 1 Day	1.0	$380.00	$380.00
	Crew Travel	1.0	$112.00	$112.00
	P&A marker	1.0	$120.00	$120.00

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211

Oil Conservation Division
State of New Mexico
1000 Rio Brazos Road
Aztec, NM 87410

July 16, 2001

Invoice #2439
Three States Navajo #1

2

Rig #4

Cement					
6-25-01		Type II Cement, 71 sxs, plug #1	71.0	$10.50	$745.50
		Pump Charge, plug #1	1.0	$550.00	$550.00
6-26-01		Type II Cement, 123 sxs, plug #2	123.0	$10.50	$1,291.50
		Type II Cement, 109 sxs, plug #3	109.0	$10.50	$1,144.50
		Pump Charge, plug #2	1.0	$550.00	$550.00
		Pump Charge, plug #3	1.0	$550.00	$550.00
6-27-01		Type II Cement,80 sxs for plug #4	80.0	$10.50	$840.00
		Pump Charge, plug #4	1.0	$550.00	$550.00
		Type II Cement, 87 sxs for plug #5	87.0	$10.50	$913.50
		Pump Charge, plug #5	1.0	$550.00	$550.00
		Type II Cement, 10 sxs for surface	10.0	$10.50	$105.00
Wireline					
6-22-01		Ran casing strip CCL	1.0	$300.00	$300.00
6-26-01		1 set HSC holes at 1345'	1.0	$550.00	$550.00
6-27-01		3 sets HSC holes at 750', 146', 96'	3.0	$550.00	$1,650.00
Transportation					
Water					
6-19-01	#1	Haul 1 load water to loc	4.0	$50.00	$200.00
6-20-01	#2	Haul 3 loads water to loc	5.0	$50.00	$250.00
6-25-01	#3	Haul water for cementing	7.0	$50.00	$350.00
6-26-01	#4	Move pit water to other location pits	4.5	$50.00	$225.00
6-27-01	#5	Move pit water to other location pits	4.0	$50.00	$200.00
Heavy Haul Truck					
6-12-01	#6	Move 400 bbl tank to location	3.0	$74.00	$222.00
	#6	Swamper	3.0	$20.00	$60.00
6-19-01	#7	Move pit, P/S, 2-7/8" basket to loc.	3.5	$74.00	$259.00
6-20-01	#8	Move 1-1/4" basket, hydraulic unit to location	3.0	$74.00	$222.00
6-21-01	#9	Haul 11" BOP to location	3.0	$74.00	$222.00
6-22-01	#10	Load mud and haul to loc, unload	3.0	$74.00	$222.00
6-27-01		Haul 1-1/4" tbg to A+ yard and 9" BOP to A+ yard	2.0	$74.00	$148.00
6-28-01	#12	Haul water tank to A+ yard	3.0	$74.00	$222.00
6-29-01	#13	Haul 9" BOP to Weatherford	1.0	$74.00	$74.00

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211

Oil Conservation Division July 16, 2001 3
State of New Mexico
1000 Rio Brazos Road **Invoice #2439** Rig #4
Aztec, NM 87410 Three States Navajo #1

Rental Equipment					
6-20/27		Water Tank	5.0	$27.00	$135.00
6-20/27		Float	5.0	$20.00	$100.00
6-20/25		Shale Shaker	3.0	$100.00	$300.00
6-20/27		2-7/8" tbg, 2410' x 5 days=12,050'	12,050.0	$0.13	$1,566.50
6-21/25		8-3/4" drill bit, 5 day minimum	1.0	$300.00	$300.00
6-20/27		Portable Toilet	8.0	$20.00	$160.00
Miscellaneous					
6-01-01	**#14**	C&C Anchor, Invoice #2187			$629.00
5-31-01	**#15**	Headrick Backhoe, Invoice #8771	2.5	$50.00	$125.00
6-11-01	**#16**	Headrick Backhoe, Invoice #8774	4.5	$50.00	$225.00
6-19-01	**#17**	Bariod, mud materials	1.0	$349.44	$349.44
	#B	Weatherford, Invoice #2x-007068-001			
		Used tools 4 days of 17 total			$870.68
	#D	Weatherford, Invoice #2X-0007342-001			
		9" BOP, rams and flanges			$1,847.65
Handling charge for the above **6 invoices - $4,046.77 at 10.0%**					$404.68
				TOTAL	$ 33,897.35
				TAX @ 6.06%	$ 2,055.03
THANK YOU				**TOTAL DUE**	**$ 35,952.37**

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

17665

Rig No 4 Date 5-31-01

Well No _____ Location Ship Rock Project Company NMOCD

FROM	TO	DESCRIPTION OF OPERATION
8:30	12:30	Continental Oil Gas, Navajo #1 Help dig out well head top, test for gas ok, cut off 10" surface 2½ feet below ground level 7" casing fell away with 12", dig out deeper cut window in 12" at 72" below ground level pushed bar through 7" with now resistance, move on to next well.
12:30	2:00	Continental Oil Gas, Navajo #2 remove plug cross threads on 2" coupling, weld 2" coupling on pipe side at ground level no gas present in well, go to next well
2:00	3:30	Three States Navajo #1 help dig out braden head, remove 2"x8" nipple from well head, gas reading very high, will return after venting for a while weld on 8" coupling

1½ hr

Welder 1½ hrs

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing _____

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor				
Operator	Fred Porter	59		7½
Helper				
Helper				
Helper				

RCI-029643-A

Date _____

17867

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

6-20-01

Rig No 4

Date Wed. [redacted]

Well No 3-states NAVAJO # Location Sec. 27, T31N, 17W Company NMOCD SHIPROCK Project

FROM	TO	DESCRIPTION OF OPERATION
9:30	9:45	Rode rig + equip to loc.
9:45	10:00	HSM on Blowing dust
10:00	11:30	RU rig
11:30	12:30	Prep 9 5/8 csg, w/valve on bradenhead, fill in hole w/dirt need 8 3/4 bit, 9" BOP, Records show no 7" csg in well, SDFD
		Henry Villanueva w/NMOCD on loc.

3 hrs

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing _____

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	B. Randall	12		
Operator	C. Escobar	16		3
Helper	R. Harrison			3
Helper	P. Fitzpatrick			3
Helper	J. Torres			3

1/2 day -

3 hrs

Date 6-13-01

RC1-029643A

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

17868

Rig No 4 Date THUR 6-21-01

Travel 1 hr

Well No 3-STATES NAVAJO #1 Location _____ Company NMOCD SHIPROCK Project

FROM	TO	DESCRIPTION OF OPERATION
6:00	6:30	load supplies
6:30	7:45	DRIVE TO LOC & HSM on whip cks
7:45	10:30	NU 9" BOP & flanges, test BOP, RU Pit & lines
10:30		PU 8¾ bit, bit-sub & X-over, strip on companion flange & stripping head, w/ 1-3½ DC, PU 3 more D.C ~~4~~ circulate hole clean at 123', (bit dragging going
	11:30	down hole)
11:30	1:00	PU tbg & tag at 1135'
1:00	1:30	circulate 9⅝ csg clean, circulating rust & scale pieces
1:30	2:00	LD tongs, PU swivel
2:00		Begin drilling at 1135', drilling fairly easy, circulating black fine sand, small pieces of scale & rust, cider fiber w/85-90 RPM, w/ 9-10,000 on 8¾ bit drilled down to 1564, started drilling hard from 1564-1595, Ream-out csg on last jt by Pulling-up 1 jt, tag bad csg at
	4:00	1585
4:00		circulate hole at 1595, circulating cider fiber, scale
	5:30	& small rocks, hole did not clean-up
5:30		POOH w/ tbg, D.C's & bit
	6:30	shut-in well
		SDFD
		1-2½" Stripping Rubber
		Henry Villanueva w/NMOCD on loc

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing _____

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	B. Randall	12		
Operator	C. Escobar	16		12½
Helper	R. Harrison			12½
Helper	P. Fitzpatrick			12½
Helper	J. Torres			12½

11.0 hr

RCI-029643A

Date 6-14-01

17869

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

6-22

Rig No 4 Date Eoi. [redacted]

Well No 3-STATES NAVAJO #1 Location _____ Company NMOCD SHIPROCK Project

1 hr Travel

FROM	TO	DESCRIPTION OF OPERATION
6:00	6:30	hold supplies
6:30	7:45	DRIVE TO LOC. HSM on Wireline
7:45		Open up well, Note: Miscounted tbg on 6-14-01
		RU A-Plus W.L. TAg at 1619' POOH w/ 24 stands (1503') + (122')
		RUN CCL from 1613 - 4 DC's + bit sub + bit = 1625' total
	9:00	to surface, found bad csg 100'-280'
9:00	10:00	TIH w/ BIT, DC's, + tbg to 1595
10:00	10:30	LD tongs, PU swivel + 1 jt
10:30	12:00	mix mud in rig pit + circulate hole w/ drilling mud
12:00		Begin drilling at 1595, circulate 1st jt down easily, drilling hard, w/ good returns of wood, old drilling mud, scale, sand, bit turning 85-90 RPM w/ 10-12,000 on 8 3/4
	4:30	bit drilled down to 1813', (54 jts + 4 DC's + B.H. sub, bit)
4:30	5:30	circulate hole clean
5:30		LD swivel, PU tong, POOH w/ 20 stands
	6:30	shut-in well
		SDFD
		2-2 7/8" Stripping Rubber
		Henry Villanueva w/ NMOCD on loc

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing _____

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	B. Randall	12		
Operator	P. Escobar	16		12½
Helper	R. Harrison			12½
Helper	P. Fitzpatrick			12½
Helper	J. Torres			12½

11.0 hr

Date 6-15-01

RCI-029643A

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

17870

6-25-01

Rig No 4 Date Mon [redacted]

Well No 3-STATES NAVAJO #1 Location _____ Company NMOCD SHIPROCK Project

One hour Travel

FROM	TO	DESCRIPTION OF OPERATION
5:30	6:00	Load supplies
6:00	7:15	DRIVE TO LOC & HSM on Handrails
7:15		Open up well @, TIH w/20 stands down to 1813'
	8:00	LD tong, P.U swivel & 1jt
8:00	8:30	circulate hole & mix mud
8:30		Begin drilling at 1813' w/10-12,000# on 8¾ bit, bit turning 85-90 RPM, good Returns, pumping 2½ bpm at 700-800#, circulating shale, scale & little rocks w/sand. drilled down to 2390 easily, hard drilling from
	2:00	2390 to 2410,
2:00		circulate hole clean at 2410', circulating cement, old
	3:15	mud & redish Rocks
3:15	3:45	LD swivel, P.U tongs, POOH with TBG & COLLARS.
3:45	5:00	P.U notch 2⅞ collar, TIH w/ tbg to 2408'
5:00		Pump 20 BBLS water down tbg, Pump Plug # 1 w/71sxs 15.6# cement (2410-2310) TOC 2310 w/100% excess, displaced w/11½bbls
	6:00	water, then 11 BBLS mud.
6:00		LD tbg upto 1689', standback 27 stands
		Shut-in well
	7:00	SDFD

1 - 2⅞" Stripping Rubber

Abb procedures Approved by Henry Villanueva w/NMOCD onloc.

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing Plug #1 71 sxs

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	B. Randall	12		
Operator	C. Escobar	16		13½
Helper	R. HARRISON			13½
Helper	P Fitzpatrick 6:30 AM			12½
Helper	J. Torres			13½

12 hrs

RCI-029643-A

Date 6-18-01

17872

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

6-26-01

Rig No 4 Date Tue. 26

Well No 3-STATES NAVAJO #1 Location _____ Company NMOCD SHIPROCK Project

FROM	TO	DESCRIPTION OF OPERATION
6:00	6:30	Head supplies
6:30	7:45	DRIVE TO LOC. + HSM on JSA
7:45	8:45	Open-up well, PU 4' plugging-sub, TIH w/ tbg to 1663'
8:45	9:15	RD PT + move, RU PT for cementing
9:15		Circulate drilling mud out w/120 BBLS water,
	10:00	circulate hole clean
10:00		Pump Plug # 2 w/ 123 sxs 15-6# cement w/2% cal.
	10:30	(1663-1430) TOC 1380'
10:30	11:00	LD tbg upto 1374, stand back 15 stands, shut-in well
11:00	2:00	WOC
2:00	~~2:20~~	TIH w/tbg, PU 2 jts + tag w/20' stick-up
		TOC at 1418'
~~2:20~~	2:30	LD 1jt + P/T 9 5/8 csg to 500# Held OK for 5mins.
2:30	3:00	LD 3 jts, stand back 21 stands (1313')
3:00	3:45	PU A-Plus w.l., Perf. at 1345 w/3-4" HSC
3:45	4:15	TIH w/ tbg, PU 1jt (tbg at 1345')
4:15		est rate in squeeze holes at 1¼ BPM at 400#
	4:45	Pump Plug # 3 w/109 sxs 15-6# cement, displace to 1054'
4:45	5:15	LD tbg to 1189', stand back 14 stands
5:15		Load hole w/4 BBLS, attempt to squeeze cement,
		pump 1 BBL, locked-up at 100#, shut-in
	5:30	SDFD
		All procedures Approved By Henry V. Manuena w/NMOCD on loc.

1 hr Travel

Fuel & Motor Oil _____ Water Hauled 2-Lds fresh water

Rental Equipment _____ Cement Retainers _____

Cementing Plug # 2 123 sxs Plug # 3 109 sxs

Wireline Perf at 1345 w/3-4" HSC

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	B. Randall	12		
Operator	C. Escobar ~~7:00~~ day-off	16		0
Helper	R. HARRISON Operator			11½
Helper	P. Fitzpatrick			11½
Helper	J. Torres			11½

10 hrs

Date 6-19-01

RCI-029643A

void # 17871

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

17873

Rig No 4 Date Wed. 27 6-27-01

Well No 3-STATE NAVAJO #1 Location _____ Company NMOC SHIPROCK Project

FROM	TO	DESCRIPTION OF OPERATION
6:00	6:30	Load supplies
6:30	7:45	DRIVE TO LOC. + HSM on JSA
7:45	8:15	OPSIN up well @ TIH w/ tbg + tag TOC at 1080'
8:15	8:45	LD tbg up to 753', standback 12 stands
8:45	8:00	Perf. at 750' w/3 4" HSC
9:00	9:15	Attempted to pump into holes at 750', pressured up to 1000#
9:15	9:30	TIH w/ tbg to 813'
9:30		Load hole 4 1/2 bbls, Pump Plug # 4 w/80sxs 15-6# cement
	10:00	(813-650) TOC 600'
10:00	10:30	LD tbg + 4 D.C's
10:30		Perf at 146' w/3 4" HSC
		Attempt to est. circulation out bradenhead, pressured up to 1000#
		Perf. at 96' w/3 4" HSC
	11:45	Attempt to est. circulation, pressured up to 1000#
11:45	12:15	P.U. tbg, tbg at 219'
12:15		Load hole 4 1/2 bbl, Pump Plug # 5 (surface) w/ 87 sxs 15.6# cement
	12:45	from 219 to surface, circulate 1 BBL good cement out csg
12:45		RD PT, + floor
	2:15	N/D BOP
2:15	2:45	Load up 3" lines + fittings + mud hopper
2:45	4:00	RD rig.
4:00		dig-out + cut-off wellhead, install dry hole marker w/10 sxs
	6:00	cut-off Anchors cement in 9 5/8 down 6'
		SDFD IN 9 5/8 X 13 3/8 down 4'
		ALL procedurizes approved by Henry U. Hanneen w/NMOCD on loc

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing Plug #4 80 sxs Plug #5 (surface) 87 sxs Plug #6 (marker) 10 sxs

Wireline Perf at 750' + 146' w/3 4" HSC, Perf at 96' w/3-4" HSC

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	B. Randall	12		
Operator	C. Escobar	16		12
Helper	R. Harrison			12
Helper	P. Fitzpatrick	110		13½
Helper	J. Torres			12

10½ hrs

Date 6-20-01

RCI-029643A

A-Plus Well Service, Inc.
P.O. Box 1979, Farmington, NM 87499
505-325-2627

2591

Date: 6-19-01 Truck #: 155

			Hours
Event: #1	From: A plus	To:	
Start: 6:00	What: Worked on Fence posts		
			4
Stop: 10:00	Charge to:		
Event: #2	From: A plus	To:	
Start: 10:00	What:		
	Pre CK 155		15
Stop: 10:30	Charge to: N.M. O.C.D		
Event: #3	From: A-plus	To: B-unit injection plant	4 hr.
Start: 10:30	What:		
	Road Time Out		1.5
Stop: 12:00	Charge to: N.M. O.C.D		
Event: #4	From: Unit B injection plant	To: 3 STATES NAVAJO #1	
Start: 12:00	What: hauled 1 bbl Filled rig pit		
			2
Stop: 2:00	Charge to: N. MOCD		
Event: #5	From: Continental Navajo #2	To: Basin Disposal	
Start: 2:00	What: hauled 1 load to Basin		
	Disposal - returned to yard		3
Stop: 5:00	Charge to: N.M. O.C.D.		
Event: #6	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #7	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #8	From:	To:	
Start:	What:		
Stop:	Charge to:		
	Driver: Lucky Mace		11
Diesel:	Helper		
Oil:	NM MILES: 46 CO MILES: _____ UT MILES: _____		

#1

Remarks:		
	NMOCD Three States #1	
	Haul 1 load water to loc	4 hrs

4 hrs

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

2592

Date: 6-20-01 Truck #: 155

Event: #1	From: A-plus To:	Hours
Start: 6:00	What: Reload Fuel with Transmission	
		1.5
Stop: 7:30	Charge to:	
Event: #2	From: A-plus To:	
Start: 7:30	What: Pre ck 155	
		.5
Stop: 8:00	Charge to: N.M. O-C.D.	
Event: #3	From: A-plus To: Continental Navajo #2	
Start: 8:00	What: Road Trip out	
		1.5
Stop: 9:30	Charge to: N.M. O-C.D.	
Event: #4	From: Continental Navajo #2 To: Three States #1	
Start: 9:30	What: Transferred 2 loads	
		3
Stop: 12:30	Charge to: N.M. O-C.D.	
Event: #5	From: Unit B injection plant To: ~~Other~~ orphan #1	
Start: 12:30	What: hauled 1 load	
		2
Stop: 2:30	Charge to: N.M. O.C.D.	
Event: #6	From: ~~Other~~ orphan #1 To: Hi plnc	
Start: 3:30	What: Road Trip in - took 155	
	To Gomes Front end shop	2
Stop: 4:30	Charge to: N.M. O.C.D.	
Event: #7	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #8	From: To:	
Start:	What:	
Stop:	Charge to:	
	Driver: Lucky Maez	10.5
Diesel:	Helper	
Oil:	NM MILES: 46 CO MILES: _____ UT MILES: _____	

Remarks:

NMOCD Three States #1

Transfer 2 loads and

haul 1 load water

5 hrs.

#2

5 hrs.

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

2630

Date: 6-25-01 Truck #: 145

Event: #1	From: A plus To:	Hours
Start: 6:00	What: Pre Trip 145	
		1.5
Stop: 6:30	Charge to: N.M. O.C.D.	
Event: #2	From: Kennington hydrant To: Three States Navajo #1	
Start: 2:30	What:	
	Road Time Out	1.5
Stop: 8:00	Charge to: N.M. O.C.D.	
Event: #3	From: Three States Navajo #1 To:	
Start: 8:00	What: unload into pump truck	
		1.5
Stop: 9:30	Charge to: N.M. O.C.D.	
Event: #4	From: Unit B injection plant To: Orphan #2	
Start: 9:30	What: hauled in loads	6.5
Stop: 4:00	Charge to: N.M.	
Event: #5	From: Three States Navajo #1 To:	
Start: 4:00	What: Transport water to pump Truck	
	For Cement Plug	2.5
Stop: 6:30	Charge to: N.M.	
Event: #6	From: Three States Navajo #1 To: A+	
Start: 6:30	What:	
	Road Time In	1.5
Stop: 8:00	Charge to: N.M. O.C.D.	
Event: #7	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #8	From: To:	
Start:	What:	
Stop:	Charge to:	
	Driver: Ruby Mares	14
Diesel:	Helper	
Oil:	NM MILES: 46 CO MILES: _____ UT MILES: _____	

Remarks:		
	NMOCD Three States Navajo #1	
	Haul water for cementing	

3 hrs

4 hr

#3

7 hrs

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

2631

Date: 6-26-01 Truck #: 165

Event: #1	From: A plus To:	Hours
Start: 6:00	What: Pre CK	
		1.5
Stop: 6:30	Charge to:	
Event: #2	From: Farmington hydrant To: A plus yard	
Start: 6:30	What:	1.5
	watered Down weeds	
Stop: 8:00	Charge to:	
Event: #3	From: A-plus To: Lesly K #1	
Start: 8:00	What: hauled 2 load From Farmington	2
	hydrant	
Stop: 10:00	Charge to: NORMAN GILBREATH	
Event: #4	From: A-plus To: Three States Navajo #1	
Start: 10:00	What:	
	Road Time Out	1.5
Stop: 11:30	Charge to: N.M. OCD	
Event: #5	From: Three states Navajo #1 To: Continental Navajo #1	
Start: 11:30	What: Transfered pit water To C.N. #1 + C.N. #2	
		3
Stop: 2:30	Charge to: NM. O.C.D.	
Event: #6	From: Orphan #2 To: Three States #1	
Start: 2:30	What: hauled 2 load	
		2.5
Stop: 5:00	Charge to: NM OCD	
Event: #7	From: Three States #1 To: A-plus	
Start: 5:00	What:	
	Rode in with Crew	1
Stop: 6:00	Charge to: N.M. O.C.D.	
Event: #8	From: To:	
Start:	What:	
Stop:	Charge to:	
	Driver: Lucy	12
Diesel:	Helper	
Oil:	NM MILES: 50 CO MILES: UT MILES:	

Remarks:	
	NMOCD Three States Nav #1
	Move pit water to other
	location pits

#4

4 1/2 hr

A-Plus Well Service, Inc.
P.O. Box 1979, Farmington, NM 87499
505-325-2627

2593

Date: 6-27-01 Truck #: 165

Event: #1	From: A-plus To:	Hours
Start: 6:00	What: Pre CK 121	
		.5
Stop: 6:30	Charge to: N.M. OCD	
Event: #2	From: A-plus To: Three States #1	
Start: 6:30	What: Road Trip Out	1.5
Stop: 8:00	Charge to: NMOCD	
Event: #3	From: Three States Navajo #1 To: Continental Navajo #2	
Start: 8:00	What: Transfered pit water	4 hr
		1
Stop: 9:00	Charge to: N.M. OCD	
Event: #4	From: Continetal Navajo #1 To: Farmington Hydrat	
Start: 9:00	What:	
	Road Time in	1.5
Stop: 10:30	Charge to: NM. OCD	
Event: #5	From: Farmington Hydrat To: Lesley K #1	
Start: 10:30	What: hauled 1 load - returned to yard	1.5
Stop: 12:00	Charge to: NORMAN GILBREATH	
Event: #6	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #7	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #8	From: To:	
Start:	What:	
Stop:	Charge to:	
	Driver: Leroy Mayer	6
Diesel:	Helper	
Oil:	NM MILES: 26 CO MILES: UT MILES:	

Remarks:		
	NMOCD Three States Nav #1	#5
	Move pit fluid to	
	other ~~pits~~ wells pits	4 hr

A-Plus Well Service, Inc.
P.O. Box 1979, Farmington, NM 87499
505-325-2627

2703

Date: 6-12-01 Truck #: 152

Event: #1	From: A-Plus Yard To: Con. Navajo #2	Hours
Start: 6:30	What: Travel Time OUT	
Stop: 8:00	Charge to: New Mexico OCD	1.5
Event: #2	From: Con Navajo #2 To: Con. Navajo #1	
Start: 8:00	What: 2⅞ Tubing, P-T & Swivel, Generator	
Stop: 11:00	Charge to: New Mexico OCD	3
Event: #3	From: Con Navajo #2 To: 3 States Navajo #1	
Start: 11:00	What: 400 bbl Tank	
Stop: 12:00	Charge to: New Mexico OCD	1
Event: #4	From: 3 States Navajo #1 To: A-Plus Yard	
Start: 12:00	What: Travel Time IN	
Stop: 2:00	Charge to:	2
Event: #5	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #6	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #7	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #8	From: To:	
Start:	What:	
Stop:	Charge to:	
	Driver: Robert B. Stuart	7.5
Diesel:	Helper Larry McKinzie	7.5
Oil:	NM MILES: 60 CO MILES: — UT MILES: —	

3 hr

#6

Remarks:	
	NMOCD Three States Navajo #1
	Haul water tank to loc

3 hr

A-Plus Well Service, Inc.

P.O. 3ox 1979, Farmington, NM 87499
505-325-2627

2884

6-19-01

Date:

Truck #: 152

			Hours
Event: #1	From: A-PLUS	To:	1/2
Start: 6:00	What: PRETRIP		
Stop: 6:30	Charge to: A-PLUS		
Event: #2	From: A-PLUS	To: CONT. NAVAJO #2	4 1/2
Start: 6:30	What: HAUL & DROP FLOAT #98 10/1 1/4 WORKSTRING, MOVE		
	2 7/8 WS, PWR. SWV. & PIT TO THREE STATES NAV #1		2 1/2
Stop: 11:00	Charge to: NMOCD		
Event: #3	From: THREE STATES NAV #1	To: A-PLUS	1
Start: 11:00	What: TRAVEL		1
Stop: 12:00	Charge to: NMOCD		3 1/2
Event: #4	From: A-PLUS	To:	2 1/2
Start: 12:00	What: PICKUP PARTS, UNIT-95 MAKE PIGTAIL, REPAIR		
	WIRING, ATTMPT TO FIND SHORT IN TAILLIGHTS		
Stop: 2:30	Charge to: A-PLUS		
Event: #5	From: A-PLUS TO CAVE INTO	To: A-PLUS	1
Start: 2:30	What: PICKUP JOINT 7" CASING		
Stop: 3:30	Charge to: NMOCD		
Event: #6	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #7	From:	To:	
Start:	What:		
Stop:	Charge to:		
Event: #8	From:	To:	
Start:	What:		
Stop:	Charge to:		
	Driver: STEVE ANDERSON		9 1/2
Diesel:	Helper		
Oil:	NM MILES: 55 CO MILES:	UT MILES:	

#7

Remarks:		
	NMOCD Three States Navajo #1	
	move pit, P/S, 2 7/8" basket	3 1/2 hr.
	to location	

A-Plus Well Service, Inc.
P.O. Box 1979, Farmington, NM 87499
505-325-2627

2885

Date: 6-20-01 Truck #: 152

Event: #1	From: A-PLUS To: BUBBLE CITY	Hours
Start: 6:00	What: PRETRIP - FUEL - FINISH FIND SHORT IN WIRING	2
	ON UNIT-95 - FINISH LIGHT REPAIRS - ALL LIGHTS WORKING	
Stop: 8:00	Charge to: A-PLUS	
Event: #2	From: A-PLUS To: NMOCD WELLS	3
Start: 8:00	What: FINISH RIG MOVE, MOVE 1¼ WORK STRING & HYD UNIT	
	TO 3 STATES NAV. #1, MOVE H2O TANK HOL. TO ORPHAN NAV. #1	
Stop: 11:00	Charge to: NMOCD	
Event: #3	From: ORPHAN NAVAJO #2 To: A-PLUS	1
Start: 11:00	What: TRAVEL	
Stop: 12:00	Charge to: NMOCD	
Event: #4	From: A-PLUS To CROSS TEMBERS To: A-PLUS	½
Start: 12:00	What: TO CROSS TEMBERS YARD TO UNLOAD PUMP JACK	
	ALREAD UNLOADED RETURN TO YARD	
Stop: 12:30	Charge to: CROSS TEMBERS	
Event: #5	From: A-PLUS To:	3
Start: 12:30	What: REPLACE HEATER VALVE UNIT-152, TS TO FIND	
	SHORT IN JAKE BRAKE, PICKUP PARTS	
Stop: 3:30	Charge to: A-PLUS	
Event: #6	From: A+ TO WEATHERFORD To: A-PLUS	½
Start: 3:30	What: TO W.F. LOAD BOP & COMP. TO YARD	
Stop: 4:00	Charge to: NMOCD	
Event: #7	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #8	From: To:	
Start:	What:	
Stop:	Charge to:	
	Driver: STEVE ANDERSON	10
Diesel:	Helper	
Oil:	NM MILES: 55 CO MILES: UT MILES:	

Remarks:	Three States Nav #1
	NMOCD
	Move 1¼" pipe basket, hydraulic
	unit to loc.
	Load 11" BOP @ Weatherford

24 1 hr 3 hrs. 1/2 #8 3 hrs 1/2 3½ hrs

A-Plus Well Service, Inc. 2886
P.O. Box 1979, Farmington, NM 87499
505-325-2627

Date: 6-24-01 Truck #: 152

Event: #1	From: A-PLUS To:	Hours
Start: 6:00	What: PRETRIP	1/2
Stop: 6:30	Charge to: A-PLUS	
Event: #2	From: A-PLUS To: 3 STATES NAV. #1	1 1/2
Start: 6:30	What: HAUL BOP + SPOOLS + COMP.	
Stop: 8:00	Charge to: NMOCD	
Event: #3	From: 3 STATES NAV. #1 To: A-PLUS	1 1/2
Start: 8:00	What: UNLOAD B.O.P. + ECT, TRAVEL TO YARD	
Stop: 9:30	Charge to: NMOCD	
Event: #4	From: ~~A-PLUS~~ PHYLLIS HARTMAN #1 To: PHYLLIS HARTMAN #1	1
Start: 9:30	What: TRAVEL LOAD FLOAT # 99 w/ 10 jts 2 3/8" TBG	
Stop: 10:30	Charge to: MANANA	
Event: #5	From: PHYLLIS HARTMAN #1 To: MANANA #1 TO A-PLUS	1
Start: 10:30	What: HAUL + UNLOAD TBG, HAUL EMPTY FLOAT	
	TO YARD	
Stop: 11:30	Charge to: MANANA	
Event: #6	From: A-PLUS TO PHYLLIS HARTMAN #1 To: AUNT MAGGIE #1 TO	2
Start: 11:30	What: 2 TRIPS MOVE 500 bbl CIRC. PIT + H2O TANK 213	
Stop: 1:30	Charge to: MANANA	
Event: #7	From: AUNT MAGGIE #1 To: BUBBLE CITY	1/2
Start: 1:30	What: TRAVEL	
Stop: 2:00	Charge to: MANANA	
Event: #8	From: BUBBLE CITY To: A-PLUS	1 1/2
Start: 2:00	What: WASH UNIT-152	
Stop: 3:30	Charge to: A-PLUS	
	Driver: STEVE ANDERSON	9 1/2
Diesel:	Helper	
Oil:	NM MILES: 70 CO MILES: _____ UT MILES: _____	

3 hrs.

(#9)

Remarks:	
	NMOCD Three States Nav #1
	Haul 11" BOP to loc.

3 hrs.

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

2887

Date: 6-27-01 Truck #: 152

Event: #1	From: A-PLUS To:	Hours
Start: 6:00	What: PRETRIP - FINISH SERVICE UNIT-161, FIRE WATCH BACK YARD	2
Stop: 8:00	Charge to: A-PLUS	
Event: #2	From: A-PLUS To: BAROLD	1/2
Start: 8:00	What: TRAVEL - LOAD 1 PALLET GEL, 6 SX SODA-ASH	
Stop: 8:30	Charge to: NMOCD	
Event: #3	From: BAROLD To: 3 STATES NAVAJO #1	1 1/2
Start: 8:30	What: HAUL + UNLOAD GEL	
Stop: 10:00	Charge to: NMOCD	
Event: #4	From: 3-STATES NAVAJO #1 To: A-PLUS	1
Start: 10:00	What: TRAVEL	
Stop: 11:00	Charge to: NMOCD	
Event: #5	From: A-PLUS - MANANA YARD To: AUNT MAGGIE #1	1
Start: 11:00	What: TRAVEL - LOAD 5 jts 1 1/4 ST+C HAUL TO LOC + UNLOAD	
Stop: 12:00	Charge to: MANANA	
Event: #6	From: AUNT MAGGIE #1 To: A-PLUS	1/2
Start: 12:00	What: TRAVEL	
Stop: 12:30	Charge to: MANANA	
Event: #7	From: ACM To:	1
Start: 12:30	What: GET FORKLIFT CERTIFICATION	
Stop: 1:30	Charge to: A-PLUS	
Event: #8	From: To:	
Start:	What:	
Stop:	Charge to:	
	Driver: STEVE ANDERSON	7 1/2
Diesel:	Helper	
Oil:	NM MILES: 78 CO MILES: UT MILES:	

Remarks:	
	NMOCD Three States Navajo #1
	Load Mud material i haul
	to location, unload

3 hrs

#10

3 hrs

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

2890

Date: 6-29-01 Truck #: 152

Event: #1	From: A-PLUS To:	Hours
Start: 6:00	What: ASST FRED IN STALL HOOD ON CEMENT TRK	6
	REMOVE SLIDE PLATE FROM FIFTH WHEEL, STEAM + INSP	
Stop: 12:00	Charge to: FOR FLOAT 95, PICKUP PARTS ET, A-PLUS	
Event: #2	From: A-PLUS - 3 STATES N.M. To: ORPHAN #2 ~~Navajo~~ To A-PLUS	4
Start: 12:00	What: MOVE + SPOT 2 7/8 WORK STRING FLOAT 106, MAKE	
	FLOAT 95 + UNLOAD 7" PIPE, LOAD 9" BOP + COMP HALLI TOOLS	
Stop: 4:00	Charge to: NMOCD	
Event: #3	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #4	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #5	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #6	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #7	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #8	From: To:	
Start:	What:	
Stop:	Charge to:	
	Driver: STEVE ANDERSON	10
Diesel:	Helper	
Oil:	NM MILES: 55 CO MILES: _____ UT MILES: _____	

2 hrs.

#11

Remarks:	
	NMOCD Three States Nav #1
	Haul 1 1/4" tbg to A+ yard
	Haul 9" BOP to A+ yard.

2 hrs

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499
505-325-2627

2891

Date: 6-28-01 Truck #: 152

Event: #1	From: A-PLUS To:	Hours
Start: 6:00	What: PRETRIP	1/2
Stop: 6:30	Charge to: A-PLUS	
Event: #2	From: A-PLUS To: ORPHAN NAVAJO #2	2
Start: 6:30	What: TO LOCATION, PULL RIG OUT,	
Stop: 8:30	Charge to: NMOCD	
Event: #3	From: ORPHAN NAVAJO #2 To: 3 STATES NAVAJO #1	1
Start: 8:30	What: TRAVEL LOAD WELLHEAD + H2O TANK #405	
Stop: 9:30	Charge to: NMOCD	
Event: #4	From: 3 STATES NAVAJO #1 To: A-PLUS	2
Start: 9:30	What: HAUL + UNLOAD H2O TANK + WELLHEAD	
Stop: 11:30	Charge to: NMOCD	
Event: #5	From: A-PLUS - LESLIE K #1 To: A-PLUS	1 1/2
Start: 11:30	What: TRAVEL - LOAD H2O TANK 213, HAUL TO	
	YARD + UNLOAD	
Stop: 1:00	Charge to: NORMAN GILBRETH	
Event: #6	From: A-PLUS To:	3
Start: 1:00	What: LOAD HAUL + EMPTY SCRAP IRON BIN,	
	PICKUP UNIT-155 AT GENE'S, WASH UNIT 152	
Stop: 4:00	Charge to:	
Event: #7	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #8	From: To:	
Start:	What:	
Stop:	Charge to:	
	Driver: STEVE ANDERSON	10
Diesel:	Helper	
Oil:	NM MILES: 75 CO MILES: _____ UT MILES: _____	

#12

Remarks:	
	NMOCD Three States Haul #1
	- 1 Fuel Water Tank to
	A+ yard

3 hrs.

A-Plus Well Service, Inc. 2892

P.O. Box 1979, Farmington, NM 87499
505-325-2627

Date: 6-29-01 Truck #: 152

		Hours
Event: #1	From: A-PLUS To:	1/2
Start: 6:00	What: PRETRIP	
Stop: 6:30	Charge to: A-PLUS	
Event: #2	From: A-PLUS To: WEATHERFORD	1
Start: 6:30	What: LOAD 11" 3m BOP STACK, FLANGE + STUDS	
	HAUL + UNLOAD	
Stop: 7:30	Charge to: NMOCD 3 STATES NAVAJO #1	
Event: #3	From: WEATHERFORD TO ORPHAN NAVAJO #1 To: A-PLUS	2 1/2
Start: 7:30	What: TO LOCATION, LOAD FLOAT 95 HAUL TO	
	YARD	
Stop: 10:00	Charge to: NMOCD	
Event: #4	From: A-PLUS To:	4 1/2
Start: 10:00	What: MINOR REPAIR UNIT-152, DROP FLOAT 98, LOAD	
	FLOAT 99 W/SCRAP IRON BIN, TAKE + PICKUP 152 MACK FINISH REPAIRS	
Stop: 2:30	Charge to: A-PLUS	
Event: #5	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #6	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #7	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #8	From: To:	
Start:	What:	
Stop:	Charge to:	
	Driver: STEVE ANDERSON -1/2 HR LUNCH	8
Diesel:	Helper	
Oil:	NM MILES: 42 CO MILES: _____ UT MILES: _____	

Remarks:	
	NMOCD Three States Nav #1
	Return 9" BOP to Weatherford

#13

1/4



C&C ANCHOR SERVICE

2187

P.O. Box 5942
Farmington, NM 87499-5942

Mobile (505) 320-8455 • Pager (505) 324-4724 • Fax (505) 632-1483



Date: 6 / 1 / 2001

To: A-Plus Well Service,Inc.

INVOICE TICKET #1581

COMPANY REPRESENTATIVE	AFE #	CODE #
Bill Randell		2001212775

QUANTITY	DESCRIPTION	UNIT PRICE	AMOUNT
#1581	State of N.M. - Three States Navajo #1		629 00

#M

Thank You For Your Business

SUB-TOTAL	629 00
5.750% TAX	36 17
TOTAL	665 17

TERMS: Net 30 Days. Interest Charged at the Rate of 2% PER MONTH or 24% PER ANNUM on Accounts not paid within 30 days.

san juan repro Form

8771

Ron Hedrick

NMOCD Bill Randel

CUSTOMER'S ORDER NO. Three States Navajo #1 | DEPT. Rig #4 | DATE: 5-31-01

NAME: Farmington, New Mexico

ADDRESS:

CITY, STATE, ZIP

SOLD BY:	CASH	C.O.D.	CHARGE	ON ACCT.	MDSE RTD.	PAID OUT

QUANTITY		DESCRIPTION	PRICE	AMOUNT
2½ hr	1	Backhoe Rent) Dig out	50.00	125.00
	2	well + clear for Pit A		
	3	Operation		
	4	Total		125.00
	5			
	6			
	7			
	8			
	9			
	10			
	11			
	12			
	13			
	14			
	15			
	16			
	17			
	18			

RECEIVED BY:

#15

KEEP THIS COPY FOR YOUR RECORDS

©1998 REDIFORM® 5L320

8774

Ron Headrick

NMOCD Bill Rondel

CUSTOMER'S ORDER NO.	DEPT.	DATE:
Four States Navajo #1	Reg #4	6-11-01

NAME: A-Plus Well Service

ADDRESS: Farmington New Mexico

CITY, STATE, ZIP

SOLD BY:	CASH	C.O.D.	CHARGE	ON ACCT.	MDSE RTD.	PAID OUT

#16

QUANTITY		DESCRIPTION	PRICE	AMOUNT	
4 1/2 hr	1	(Back hoe Rent) Back	50 00	225	00
	2	Fill around well head			
	3	& dig Pit for PtA Operation			
	4	Total		225	00
	5				
	6				
	7				
	8				
	9				
	10				
	11				
	12				
	13				
	14				
	15				
	16				
	17				
	18				

RECEIVED BY:

KEEP THIS COPY FOR YOUR RECORDS

©1998 REDIFORM® 5L320

Invoice

Halliburton Energy Services, Inc.
P.O. Box 1675, Houston, TX 77251
Phone: (281) 871-5900

DRILLING [illegible]

PLEASE REMIT TO:
Halliburton Energy Services, Inc.
P.O. Box [illegible]
Houston, TX 77261-[illegible]

SOLD TO
A-PLUS WELL SERVICE INC
P O BOX [illegible]
FARM. NM [illegible]

(SAME AS "SOLD TO" UNLESS OTHERWISE SHOWN)

SHIP TO
A-PLUS WELL SERVICE INC

Please quote our invoice number.

For Invoice Inquiries
Please call: 281-871-8237

DATE	INVOICE NUMBER	PAGE
6/26/01	0343[illegible]	1

CUSTOMER REFERENCE NUMBER	WELL CODE	CUSTOMER NO.	TERMS	SHC	COPIES
		2[illegible]	Due on 07/15/01		1

PRODUCT NUMBER	DESCRIPTION	QUANTITY SHIPPED	PRICING QUANTITY	UNIT PRICE	PR UNIT	AMOUNT
MISC. CHGS TO BE SUPPLIED.						
[illegible]	GELQUIK-GEL	[illegible]	[illegible]	[illegible]	SHG	280.00
[illegible]	BENTONITE ASH	[illegible]	[illegible]	[illegible]	SHG	48.40
[illegible]	CHLORIDE PELLET	[illegible]	[illegible]	[illegible]	EA	10.00
[illegible]	SHRINK WRAP	[illegible]	[illegible]	[illegible]	EA	10.20

$349.44

Shipping Document: 0343[illegible]
FOB Warehouse FARMINGTON NM
Shipped 06/26/01 VIA CUSTOMER PICKUP

		Taxable $	Tax Rate	
NEW MEXICO	State Tax	[illegible]	[illegible]	15.71
SAN JUAN	County Tax	[illegible]	[illegible]	1.31
FARMINGTON	City Tax	[illegible]	[illegible]	4.16

#17

TOTAL 370.62

TERMS: If customer does not have an approved account with Halliburton, all sums due are payable in cash at the time of performance of services or delivery of equipment, products or materials. If Customer has an approved open account with Halliburton, invoices are payable on the twentieth day after date of invoice. Customer agrees to pay interest on any unpaid balance from the date payable until paid at the highest lawful contract rate applicable, but never to exceed 18% per annum. In the event Halliburton employs an attorney for collection of any account, Customer agrees to pay attorney fees of 20% of the unpaid account, plus all collection and court costs. All services, equipment, products and materials supplied hereunder

Weatherford

Inv Seq#: 2X 001 * BILLING APPROVAL * PAGE 1 of 3

ite: 17-JUL-2001 Final Bill

Supplied By: FARMINGTON
Wh Phone #: 505-327-6341
Ordered By: BILL CLARK,
Contract:
PO:
AFE:
Service Tkt:_____

Field:
Lease: NMOCD SHIPROCK PROJECT
Well:
Rig: A-PLUS 4
Ocs:
Job Typ: RENTALS-MISC.RENTAL TOO
PBook: 2000US

Bill To: 534221
Del Tkt: 2X-0007068-001
Shp Via: CUST
Rtn Via: CUST
Svc Rte: STD
State: NM
County: SAN JUAN
City: <none>

-PLUS WELL SERVICE INC
.O. BOX 1979

ARMINGTON,NM 87499 USA

Item#/ Seq- Line	Reference Code/ Description/ Serial Numbers/Description	Ship Return	Qty	Bill Days Units UOM	Unit Price Stdby Disc%	Gross Amount Disc %	Extended Amount	
Equipment *								
-1	2 010000050005 DRILL COLLAR, SLICK, 3-1/8" OD W/2-7/8" PAC BILL FROM 29-MAY-2001 TO 19-JUN-2001	29-MAY 19-JUN	4	Min-> 5.00 Add-> 11.00 4.0000 EA	180.00 18.00	1512.00 20.00%	1209.60	*
-2	3 033500200015 SUB, LIFT, 2-7/8" CONN & SMALLER 5889 - 2-7/8" PAC 2-3/8" S/S BILL FROM 29-MAY-2001 TO 19-JUN-2001	29-MAY 19-JUN	1	Min-> 5.00 Add-> 11.00 1.0000 EA	73.00 11.00	194.00 20.00%	155.20	*
-3	4 033500200015 SUB, LIFT, 2-7/8" CONN & SMALLER 52217 - 2-7/8" PAC 2-3/8" S/S BILL FROM 29-MAY-2001 TO 19-JUN-2001	29-MAY 19-JUN	1	Min-> 5.00 Add-> 11.00 1.0000 EA	73.00 11.00	194.00 20.00%	155.20	*
-4	5 009000200005 CLAMP, SAFETY TYPE "T" (NON-SERIALIZED) 5 LINK TYPE "T" SAFTY CLAMP #4573 BILL FROM 29-MAY-2001 TO 19-JUN-2001	29-MAY 19-JUN	1	Min-> 5.00 Add-> 11.00 1.0000 EA	220.00 36.00	616.00 20.00%	492.80	*
-5	6 033500100005 SUB, FLOAT, 3-1/2" CONN X 2-3/8" CONN & SML 5069 - 3-1/2" REG BOX X 2-7/8" PAC BOX (BFF) BILL FROM 29-MAY-2001 TO 19-JUN-2001	29-MAY 19-JUN	1	Min-> 5.00 Add-> 2.00 1.0000 EA	99.00 19.00	137.00 20.00%	109.60	*
	7 033500350010							

B-1

ORIGINAL EQUIPMENT AND SERVICES ARE PROVIDED SUBJECT TO TERMS AND CONDITIONS ON REVERSE INCLUDING INSURANCE INDEMNITY RELEASE HOLD HARMLESS AND WARRANTY DISCLAIMER

Weatherford

Inv Seq#: 2X 001 * BILLING APPROVAL * PAGE 2 of 3

Item#/ Seq- Line	Reference Code/ Description/ Serial Numbers/Description	Ship Return	Qty	Bill Days Units UOM	Unit Price Stdby Disc%	Gross Amount Disc %	Extended Amount
-6	SUB, BOX X PIN, 2-7/8" CONN X 2-7/8" CONN	29-MAY 06-JUN	1	Min-> 3.00 Add-> 4.00 1.0000 EA	37.00 11.00	81.00 20.00%	64.80 *
	7374138 - 2-7/8" EUE 8RD BOX X 2-7/8" PAC PIN BILL FROM 29-MAY-2001 TO 06-JUN-2001						
8	033500350010						
-1	SUB, BOX X PIN, 2-7/8" CONN X 2-7/8" CONN	06-JUN 19-JUN	1	Min-> 3.00 Add-> 2.00 1.0000 EA	37.00 11.00	59.00 20.00%	47.20 *
	48428 - 2-7/8" EUE 8RD BOX X 2-7/8" PAC PIN BILL FROM 06-JUN-2001 TO 19-JUN-2001						
9	033500100005						
-1	SUB, FLOAT, 3-1/2" CONN X 2-7/8" CONN	12-JUN 19-JUN	1	Min-> 5.00 Add-> 1.0000 EA	99.00 19.00	99.00 20.00%	79.20 *
	148803 - 3-1/2" REG BOX X 2-7/8" PAC BOX (BFF) BILL FROM 12-JUN-2001 TO 19-JUN-2001						
10	033500350010						
-2	SUB, BOX X PIN, 2-7/8" CONN X 2-7/8" CONN	12-JUN 19-JUN	1	Min-> 3.00 Add-> 2.00 1.0000 EA	37.00 11.00	59.00 20.00%	47.20 *
	3056 - 2-7/8" EUE 8RD BOX X 2-7/8" PAC PIN BILL FROM 12-JUN-2001 TO 19-JUN-2001						
21	033500350020						
-11	SUB, BOX X BOX, 4-1/2" CONN X 2-3/8" CONN & SML	14-JUN 19-JUN	1	Min-> 3.00 Add-> 2.00 1.0000 EA	58.00 17.00	92.00 20.00%	73.60 *
	156049 - 4-1/2" REG BOX X 2-3/8" IF (NC-26) BOX BILL FROM 14-JUN-2001 TO 19-JUN-2001						
Sales	*						
25	SUB, FLOAT, 3-1/2" CONN X 2-3/8" CONN & SML	29-MAY 19-JUN	1	Min-> Add-> 1.0000 EA	.00 522.00	522.00	522.00 *
	5069 - 3-1/2" REG BOX X 2-1/2" MOD BOX (BFF)						
26	SUB, BOX X PIN, 2-7/8" CONN X 2-7/8" CONN	29-MAY 06-JUN	1	Min-> Add-> 1.0000 EA	.00 344.00	344.00	344.00 *
	7374138 - 2-7/8" EUE 8RD BOX X 2-7/8" PAC PIN						

B-2

ORIGINAL EQUIPMENT AND SERVICES ARE PROVIDED SUBJECT TO TERMS AND CONDITIONS ON REVERSE INCLUDING INSURANCE INDEMNITY RELEASE HOLD HARMLESS AND WARRANTY DISCLAIMER

07/15/2001 22:04 5053247/503

Weatherford

Inv Seq#: 2X 001 * BILLING APPROVAL * PAGE 3 of 3

Item#/ Seq-Line	Reference Code/ Description/ Serial Numbers/Description	Ship Return	Qty	Bill Days Units UOM	Unit Price Stdby Disc%	Gross Amount Disc %	Extended Amount
Other *							
27	Z00500150035 INSPECTION CHARGES-WEATHERFORD IN HOUSE CHARGES END AREA INSPECTION - 16 ENDS		1	Min-> Add-> 1.00 16.0000 EA	.00 20.00	320.00	320.00 *
28	Z00500150050 WASTE DISPOSAL CHARGES TUBULAR AND DOWNHOLE TOOLS 16 ENDS		1	Min-> Add-> 1.00 16.0000 EA	.00 1.00	16.00	16.00 *
29	ZREPAIRS MISC REPAIRS ALL SERVICES RECUT 2-7/8 EUE BOX ON #48428		1	Min-> Add-> 1.00 1.0000 EA	.00 64.00	64.00	64.00 *

Comments:
UOTED PRICES. THANK YOU FOR USING
EATHERFORD.

Subtotal:	3700.40
State Tax:	166.50
County Tax:	13.89
City Tax:	43.94
TOTAL AMOUNT DUE: US$	3924.73

Date: 17-JUL-2001

Indicates Taxed Item

Billing Approval: _____ Signature

_____ Print Name

17 day - 3700.40

4/17 = 870.68 6/17 = $1306.02

5/17 = $1088.35 2/17 = $435.34

B-3

ORIGINAL EQUIPMENT AND SERVICES ARE PROVIDED SUBJECT TO TERMS AND CONDITIONS ON REVERSE, INCLUDING INSURANCE, INDEMNITY, RELEASE, HOLD HARMLESS AND WARRANTY DISCLAIMER. PLEASE READ THEM CAREFULLY

Weatherford

Inv Seq#: 2X 001 * BILLING APPROVAL * PAGE 1 of 3

Three States Fee #1

ate: 17-JUL-2001 Final Bill

Supplied By: FARMINGTON
Wh Phone #: 505-327-6341
Ordered By: ROBERT WHITELEY,
Contract:
PO:
AFE:
Service Tkt:

Field:
Lease: ~~ORPHAN~~
Well: ~~#2~~
Rig: ~~A-PLUS~~ 4
Ocs:
Job Typ: RENTALS-MISC.RENTAL TOO
PBook: 2000US

Bill To: 534221
Del Tkt: 2X-0007342-001
Shp Via: CUST
Rtn Via: CUST
Svc Rte: STD
State: NM
County: SAN JUAN
City: <none>

-PLUS WELL SERVICE INC
.O. BOX 1979

ARMINGTON,NM 87499 USA

Item#/ Seq- Line	Reference Code/ Description/ Serial Numbers/Description	Ship Return	Qty	Bill Days Units UOM	Unit Price Stdby Disc%	Gross Amount Disc %	Extended Amount	
Equipment *								
15	004500150165							
-9	BOP, 9" 3M DBL HYD, SHAFFER	19-JUN 22-JUN	1	Min-> Add-> 1.0000 EA	4.00 1455.00 193.00	1455.00 20.00%	1164.00	*
	103272 - 9" 3M DBBLE STW W/ 11" 3M BOTTOM, 4 EA 4" 3M OUTLE BILL FROM 19-JUN-2001 TO 22-JUN-2001							
18	032500050080							
-12	SPOOL, DRILLING, 11" 2M/3M X 11" 2M/3M	19-JUN 22-JUN	1	Min-> Add-> 1.0000 EA	4.00 145.00 15.00	145.00 20.00%	116.00	*
	5403 - 18" BILL FROM 19-JUN-2001 TO 22-JUN-2001							
19	014500050020							
-13	FLANGE, COMPANION, 11" 2M/3M X 9-5/8" 8RD	19-JUN 22-JUN	1	Min-> Add-> 1.0000 EA	4.00 100.00 10.00	100.00 20.00%	80.00	*
	5034 - BILL FROM 19-JUN-2001 TO 22-JUN-2001							
20	032500050080							
-14	SPOOL, ADAPTER, 9" 3M X 7-1/16" 2M/3M	19-JUN 22-JUN	1	Min-> Add-> 1.0000 EA	4.00 145.00 15.00	145.00 20.00%	116.00	*
	2029 - 18" BILL FROM 19-JUN-2001 TO 22-JUN-2001							
21	014500050045							
-15	FLANGE, BLIND, 2-1/16" 5M	19-JUN 22-JUN	1	Min-> Add-> 1.0000 EA	4.00 70.00 10.00	70.00 20.00%	56.00	*

01

EQUIPMENT AND SERVICES ARE PROVIDED SUBJECT TO TERMS AND CONDITIONS ON REVERSE INCLUDING INSURANCE, INDEMNITY, RELEASE, HOLD HARMLESS AND WARRANTY DISCLAIMER

DI 1340

Weatherford

Inv Seq#: 2X 001 * B I L L I N G A P P R O V A L * PAGE 2 of

Item#/ Seq- Line	Reference Code/ Description/ Serial Numbers/Description	Ship Return	Qty	Bill Days Units UOM	Unit Price Stdby Disc%	Gross Amount Disc %	Extended Amount
	103295 - BILL FROM 19-JUN-2001 TO 22-JUN-2001						
22 -16	014500050045 FLANGE, COMPANION, 2-1/16" 5M x 2-3/8" 8RD	19-JUN 22-JUN	1	Min-> 4.00 Add-> 1.0000 EA	70.00 10.00	70.00 20.00%	56.00 *
	194554 - BILL FROM 19-JUN-2001 TO 22-JUN-2001						
23 -17	Z33000050010 STUDS AND NUTS (STANDARD B-7 A1-1/8" THRU 1-1/2" (EACH) - 1-3/8 X 11 BOLT W/ 2 NUT	19-JUN 22-JUN	16	Min-> 4.00 Add-> 1.0000 EA	5.00 1.00	80.00 20.00%	64.00 *
Other	BILL FROM 19-JUN-2001 TO 22-JUN-2001 *						
26	*No Price Book Reference Code Available* RING GASKET, R-53 11" 2M/3M RING GASKET, R-53 11" 2M/3M SALE		2	Min-> Add-> 1.00 1.0000 EA	.00 38.00	76.00	76.00 *
27	*No Price Book Reference Code Available* RING GASKET, R-49 9" 2M/3M RING GASKET, R-49 9" 2M/3M SALE		2	Min-> Add-> 1.00 1.0000 EA	.00 38.00	76.00	76.00 *
28	Z00500150045 WASTE DISPOSAL CHARGES PRESSURE CONTROL EQUIPMENT 3% PRESSURE CONTROL EQUIPMENT		1	Min-> Add-> 1.00 1455.0000 EA	.00 .03	43.65	43.65 *

D-2

PAGE 03/07 WEATHERFORD 5053277503 07/15/2001 22:04

ORIGINAL EQUIPMENT AND SERVICES ARE PROVIDED SUBJECT TO TERMS AND CONDITIONS ON REVERSE INCLUDING INSURANCE, INDEMNITY, RELEASE, HOLD HARMLESS AND WARRANTY DISCLAIMER

DI 7340

Weatherford

Inv Seq#: 2X 001 * BILLING APPROVAL * PAGE 3 of 3

Item#/ Seq- Line	Reference Code/ Description/ Serial Numbers/Description	Ship Return	Qty	Bill Days Units UOM	Unit Price Stdby Disc%	Gross Amount Disc %	Extended Amount

mments:
JOTED PRICES. THANK YOU FOR USING
EATHERFORD.

Subtotal:	1847.65
State Tax:	83.14
County Tax:	6.95
City Tax:	21.96
TOTAL AMOUNT DUE: US$	1959.70

Date: 17-JUL-2001

Indicates Taxed Item

Billing Approval: _____
Signature

_____
Print Name

Invoice '01-3

ORIGINAL EQUIPMENT AND SERVICES ARE PROVIDED SUBJECT TO TERMS AND CONDITIONS ON REVERSE INCLUDING INSURANCE, INDEMNITY, RELEASE, HOLD HARMLESS AND WARRANTY DISCLAIMER