Form 9–331
(May 1963)

..ITED STATES
DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

SUBMIT IN TRIP   E*
(Other instructions ᴜᴜ re-
verse side)

Form approved.
Budget Bureau No. 42–R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0268967-A

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

1.

OIL WELL ☐   GAS WELL ☐   OTHER   DRY HOLE

2. NAME OF OPERATOR

ROBERT N. ENFIELD

3. ADDRESS OF OPERATOR

POB 807, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980 FS&WL Sec. 22, T13S, R30E, NMPM
Chaves County, New Mexico

8. FARM OR LEASE NAME

Federal "22"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 22, T13S, R30E, NMP

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3948' D.F.

12. COUNTY OR PARISH   13. STATE

Chaves   New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING	X
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	
SHOOT OR ACIDIZE ☐	ABANDON*	X
REPAIR WELL ☐	CHANGE PLANS ☐	
(Other)		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other)	

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Prep to set cement plugs and cut and pull casing as follows:

100' cement plug on top of bridge plug @ 9714'.
Cut and remove 4½" casing.
100' cement plug on top 4½" stub.
100' cement plug 7600' to 7500' if 4½" stub is below 7500'.
100' cement plug 4200' to 4100'.
100' cement plug at 2027' (bottom of 8-5/8" casing)
If 8-5/8" casing is cut and removed, 100' cement plug @ stub of 8-5/8" and 100' plug @ 450' to 350'
20 sack cement plug at surface.
Install regulation marker.
Clean location.

Verbal approval for above given by Mr. James A. Knauf.

RECEIVED

JUN 26 1972

O. C. C.
ARTESIA OFFICE

JUN 23 1972
U.S. GEOL.
ARTES. OFF.

18. I hereby certify that the foregoing is true and correct.

SIGNED _Robert N. Enfield_   TITLE _Operator_   DATE 6/22/72
ROBERT N. ENFIELD

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____   DATE _____

APPROVED

JUN 23 1972

R. L. BEEKMAN
DISTRICT ENGINEER

*See Instructions on Reverse Side