Submit 1 Copy To Appropriate District Office

District I – (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II – (575) 748-1283
811 S. First St., Artesia, NM 88210
District III – (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV – (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

WELL API NO. 30-021-20539	
5. Indicate Type of Lease STATE ☐ FEE ☐ P	
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other X CO2

2. Name of Operator   Hess Corporation

3. Address of Operator PO Box 840   Seminole TX   79360

7. Lease Name or Unit Agreement Name

West Bravo Dome Unit

8. Well Number 221F

9. OGRID Number   495

10. Pool name or Wildcat
West Bravo Dome CO2 Gas

4. Well Location

Unit Letter F : 2160 feet from the N line and 1990 feet from the W line

Section 22   Township 18N   Range 29E   NMPM   County Harding

11. Elevation *(Show whether DR, RKB, RT, GR, etc.)*
5324 GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐   PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐   CHANGE PLANS ☐
PULL OR ALTER CASING ☐   MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐   ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Pref & set Frac Plug ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6/14/2012

6/14/2012 MIRU Renegade Wireline. Held prejob JSA. Tagged TD and corrected to 2996'.

Shot 2836'-2846' zone with 10' tag gun. Shot 2888'-2908' zone with 20' slick gun.

Placed frac plug between zones at 2851'. RDMO RWLS.

Spud Date: 05/19/2012

Rig Release Date: 06/14/2012

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _(signed Rita C Smith)_   TITLE Engineer Tech   DATE 07/06/2012

Type or print name Rita C Smith   E-mail address: rsmith@hess.com   PHONE: 432-758-6726

For State Use Only

APPROVED BY: _(signed)_   TITLE DISTRICT SUPERVISOR   DATE 7/17/2012
Conditions of Approval (if any):