3 Whigham bonds cannot be released as of 4/17/81.

Wells: Davis-Pinon #1 & #2; both in 21-14N-10E
Santa Fe Co.
Drilled, plugged & inspected. all OK except no C-105 forms nor logs submitted. Operator sent notice with copies of Rule 202 & 1105, on 4/7/80

Davis-Pueblo #1, M-35-1N-6W
Socorro Co.
Drilled & plugged but no log submitted. We have C-105.
Operator notified & copy of Rule 202 sent.

Davis-Pueblo #2, F-35-1N-6W
Socorro Co.
Location restored, well not drilled.

This bond (9315333) can be released.

Diane: No change in above, as of 7/21/81
" " " " " 12/1/81