District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	State of New Mexico Energy Minerals and Natural Resources Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505	Form C-141 Revised August 8, 2011 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB142263729   _260737_

OPERATOR	☒ Initial Report ☐ Final Report
Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Golden 8 Federal Battery #1, the Well #1 was P&A 2011	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-26931

LOCATION OF RELEASE

Unit Letter K	Section 8	Township 21S	Range 29E	Feet from the 1650	North/South Line South	Feet from the 2180	East/West Line West	County Eddy

Latitude N 32.491141 **Longitude** W 104.007775

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 3 Bbls of crude oil and 38 Bbls water	Volume Recovered: 1 Bbl. oil and 17 Bbls water.
Source of Release: Victaulic fitting on the production header.	Date and Hour of Occurrence: Date 8/12/14 Time unknown	Date and Hour of Discovery: Date 8/12/14 Time approximately 10:30 a.m.
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? NMOCD Emergency #104	
By Whom? Tony Savoie	Date and Hour: 8/12/14 at 12:10 p.m.	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT

AUG 1 3 2014

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A Victaulic gasket failed on the production header due to a normally open valve was shut causing pressure to build up and blow out the gasket. The gasket was replaced and the valve was returned to normal. **RECEIVED**

Describe Area Affected and Cleanup Action Taken.*
The spill impacted approximately 1500 sq. ft. of the tank battery earthen containment area. The spill impacted an area that had been cleaned up as far as practicable in the area around the vessels and lines during a remediation at the facility in August of 2011, reference 2RP-633. And the same are as impacted by spill reference 2RP-2082. The area will be re-addressed, cleaned up as required and a new closure report will be submitted including data from the previous two spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

	OIL CONSERVATION DIVISION
Signature: _Tony Savoie_	
Printed Name: Tony Savoie	Approved by Environmental Specialist: Signed By _____
Title: Waste Management and Remediation Specialist	Approval Date: 8/14/14 Expiration Date: N/A
E-mail Address: tasavoie@basspet.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached ☐
Date: 8/13/14 Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

2RP-2439