FORM C-105

RECEIVED NOV 1 1941 OCD

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELL

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work reported is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

Roswell, New Mexico (Place) October 13, 1941 (Date)

OIL CONSERVATION COMMISSION
Santa Fe, New Mexico.
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the Brown Well
R. I. Willson (Company or Operator) Byron O. Brown (Lease) Well No. 1 in the
NE¼ SE¼ of Sec. 29, T. 11S, R. 23E, N. M. P. M.,
Six Mile Hill Area Field, Chaves County

The dates of this work were as follows: Sept. and 1st part Oct.

Notice of intention to do the work was ~~(was not)~~ submitted on Form C-102 on Sept. 5, 19 41
and approval of the proposed plan was ~~(was not)~~ obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Filled hole to Total Depth, 2000 feet back to 900 feet, with mud, shot off 7 inch casing, pulled same out of hole. Set 5 sacks cement plug, filled hole with mud from 900 feet back to 715 feet. Could not pull 704 feet of 8 inch casing. Shot 8 inch casing at 660 feet, could not pull, set 5 sacks cement plug in shot hole at 660 feet on bridge. Shot again at 600 feet and 500 feet, could not pull. Filled hole with mud from 660 feet to 350 feet, shot casing at 350 feet. Could only pull casing up one joint, or 20 feet, Set cement plug, 5 sacks cement, at 350 feet, tested for hardness and was O.K. Shot casing again at 275 feet to let in surface water. 8 inch casing left in hole for water well. Filled outside of casing with rock to surface, put 5 sacks cement on top of rock out side of casing and cleaned location.

Witnessed by

Subscribed and sworn to before me this 13 day of October, 19 41

Notary Public

My Commission expires 1-20-45

I hereby swear or affirm that the information given above is true and correct.

Name R. I. Willson

Position

Representing R. I. Willson (Company or Operator)

Address Roswell, New Mexico

Remarks:

Roy Yarbrough
Name

OIL & GAS INSPECTOR
Title