Form 3160—5
(November 1983)
(Formerly 9—331)

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

NM OIL CONS. COMMISSION
SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)
Artesia, NM 88210

5. LEASE DESIGNATION AND SERIAL NO.

NM 37128

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED
JAN 23
O. C. D.
ARTESIA, OFFICE

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1.		
OIL WELL ☐	GAS WELL ☐	OTHER P&A

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

Yates Petroleum Corporation

8. FARM OR LEASE NAME

Chisum AAW Federal

3. ADDRESS OF OPERATOR

207 South 4th St., Artesia, NM 88210

9. WELL NO.

1

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

    1980 FNL & 1980 FEL, Sec. 27-T2S-R19E

10. FIELD AND POOL, OR WILDCAT

Wildcat – Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit G, Sec. 27-2S-19E

14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE
	4954' GR	Lincoln	NM

16.   ## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) _____	
(Other)		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*.

Propose to plug and abandon well as follows:

Set 100' plug 2750-2650'. Tag plug.
Set 100' plug 2360-2260'. Tag plug.
Set 100' plug 1250-1150'. Tag plug.
Set 50' plug to surface.

Notify BLM prior to plugging.
Set regulation dry hole marker. Clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED _Juanita Doublett_   TITLE Production Supervisor   DATE 1-18-85

(This space for Federal or State office use)   **APPROVED**
(Orig. Sgd.) PETER W. CHESTER

APPROVED BY _____   TITLE _____   DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 25 1985

*See Instructions on Reverse Side