STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	/
SANTA FE	/
FILE	//
U.S.G.S	
LAND OFFICE	/
OPERATOR	/

RECEIVED
OIL CONSERVATION DIVISION
P.O. Box 2088
SANTA FE, NEW MEXICO 87501 OCT 7 1982

O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐   Fee ☒

5. State Oil & Gas Lease No.

-

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS.)

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

1. OIL WELL ☐   GAS WELL ☒   OTHER

7. Unit Agreement Name

-

2. Name of Operator
Read & Stevens, Inc.

8. Farm or Lease Name
Cass Draw

3. Address of Operator
P.O. Box 1518, Roswell, NM 88201

9. Well No.
1

4. Location of Well

UNIT LETTER I . 1980 FEET FROM THE South LINE AND 990 FEET FROM

THE East LINE. SECTION 24 TOWNSHIP 23S RANGE 27E NMPM

10. Field and Pool, or Wildcat

Und. North Loving Morrow

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

XXXXXXXXXXXXXXXXXXXXXXXXXXX	5. Elevation(Show whether DF,RT,GR,etc.)	12. County	XXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXXXXXX	3087.4' GR	Eddy	XXXXXXXXXXXXXXX

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	☐	PLUG AND ABANDON	☐	REMEDIAL WORK	☐	ALTERING CASING	☐
TEMPORARILY ABANDON	☐	CHANGE PLANS	☐	COMMENCE DRILLING OPNS.	☐	PLUG AND ABANDONMENT	☐
PULL OR ALTER CASING	☐			CASING TEST AND CEMENT JOB	☐		
OTHER	☐			OTHER Squeeze			☒

Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-2-82   Set E-Z Drill @ 12,242' prep to squeeze.

10-3-82   Squeeze w/100sx Class "H" cmt w/1% Halad-9 and 50sx Class "H" cmt,
              pump into perfs @ 1 1/2 BPM @ 5800psi, cmt circ around to upper
              perfs. Pull tbg, press up to 2000psi.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____   TITLE Drilling & Production Manager   DATE 10-6-82

APPROVED BY Original Signed By
            Leslie A. Clements   TITLE _____   DATE OCT 8 1982
CONDITIONS OF APPROVAL Supervisor District II