State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE

DISTRICT I
1625 N. French Dr , Hobbs, NM 88240

DISTRICT II
1301 W Grand Ave, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

HOBBS OCD

NOV 16 2012

RECEIVED

OIL CONSERVATION DIVISION

220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-05490

5 Indicate Type of Lease STATE [X] FEE [ ]

6 State Oil & Gas Lease No

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)

7. Lease Name or Unit Agreement Name: North Hobbs (G/SA) Unit Section 24

1 Type of Well: Oil Well [X] Gas Well [ ] Other

8 Well No. 341

2 Name of Operator: Occidental Permian Ltd.

9 OGRID No 157984

3 Address of Operator: HCR 1 Box 90 Denver City, TX 79323

10 Pool name or Wildcat: Hobbs (G/SA)

4 Well Location

Unit Letter O 330 Feet From The South Line and 2310 Feet From The East Line

Section 24 Township 18-S Range 37-E NMPM Lea County

11 Elevation (*Show whether DF, RKB, RT GR, etc*) 3655' GL

Pit or Below-grade Tank Application [ ] or Closure [ ]

Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water

Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	[ ]	PLUG AND ABANDON	[ ]	REMEDIAL WORK	[X]	ALTERING CASING	[ ]
TEMPORARILY ABANDON	[ ]	CHANGE PLANS	[ ]	COMMENCE DRILLING OPNS.	[ ]	PLUG & ABANDONMENT	[ ]
PULL OR ALTER CASING	[ ]	Multiple Completion	[ ]	CASING TEST AND CEMENT JOB	[ ]		
OTHER:			[ ]	OTHER:			[ ]

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RUPU & RU.
2. RU wire line & perforate tubing @3970'. RD wire line.
3. ND wellhead/NU BOP.
4. POOH and lay down ESP equipment.
5. Run back in hole w/ESP equipment set on 125 jts of 2-7/8" tubing. Intake set @4006'
6. ND BOP/NU wellhead.
7. RDPU & RU. Clean location and return well to production.

RUPU 10/02/2012
RDPU 10/08/2012

I hereby certify that the information above is true and complete to the best of my knowledge and belief I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines [ ], a general permit [ ] or an (attached) alternative OCD-approved plan [ ]

SIGNATURE Mendy A Johnson TITLE Administrative Associate DATE 11/14/2012

TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy_johnson@oxy.com TELEPHONE NO. 806-592-6280

For State Use Only

APPROVED BY _____ TITLE Dist Mgr DATE 11/19/2012

CONDITIONS OF APPROVAL IF ANY:

November 13, 2012

Work Plan Report for Well:NHSAU 341-24



Survey Viewer