Form 3160-5
(April 2005)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Hobbs

HOBBS OCD

FEB 04 2013

RECEIVED

FORM APPROVED
Budget Bureau No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE – Other instructions on reverse side.

5. Lease Serial No.
SWD ROW NM-086

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement, Name and/or No.

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ SWD

8. Well Name and No.
Government 'E' Well No. 1

2. Name of Operator
Agua Sucia LLC

9. API Well No.
30-025-23708

3a. Address
5708 W. Austin, Broken Arrow, OK 74011

3b. Phone No. (include area code)
918-704-5552

10. Field and Pool, or Exploratory Area
SWD; Bone Spring

4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)
610' FSL & 1880' FWL, SW/SW, Unit Ltr N, Sec. 25, T-19S, R34E, NMPM

11. County or Parish, State
Lea County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☒ Other **Clean out well to reduce pressure**
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be Filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

CLEAN OUT WELL TO REDUCE PRESSURE FROM 1940# TO NOMINAL PRESSURE

POOH with tbg. and pkr. Clean out well to PBTD, 10277'. Acidize well. Notify OCD 24 hrs. prior to running pressure test. Return to injection.

LIKE SUNDRY ALSO SUBMITTED TO OCD

14. I hereby certify that the foregoing is true and correct
Name (*Printed/Typed*) Debbie McKelvey — Title Agent

Signature Debbie McKelvey — Date 1/14/13

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

APPROVED
MAR 29 2013
/s/ Chris Walls
BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

Approved by — Title — Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. — Office

ECG 2-5-2013

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, Fictitious or fraudulent statements or representations as to any matter within its jurisdiction

FEB 05 2013