HOBBS OC

MAR 1 4 2014

RECEIVED

OCD Hobbs

Form 3160- 5
(August, 2007)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004- 0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE *- Other Instructions on page 2.*

5. Lease Serial No.
NMLC064198A

6. If Indian, Allottee, or Tribe Name

7. If Unit or CA. Agreement Name and/or No.
NMNM70982X

1. Type of Well
[X] Oil Well [ ] Gas Well [ ] Other

8. Well Name and No.
Lusk Deep Unit A #28H

2. Name of Operator
COG Operating LLC

9. API Well No.
30-025-41291

3a. Address
2208 W. Main Street
Artesia, NM 88210

3b. Phone No. *(include area code)*
575-748-6946

10. Field and Pool, or Exploratory Area
Lusk; Bone Spring

4. Location of Well *(Footage, Sec., T., R., M., or Survey Description)*
SHL: 430' FSL & 330' FWL, Lot 4 (SWSW) Sec 18-T19S-R32E
BHL: 382' FSL & 339' FEL, Unit P (SESE) Sec 18-T19S-R32E

Lat.
Long.

11. County or Parish, State
Lea NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
[ ] Notice of Intent	[ ] Acidize	[ ] Deepen	[ ] Production (Start/ Resume)	[ ] Water Shut-off
	[ ] Altering Casing	[ ] Fracture Treat	[ ] Reclamation	[ ] Well Integrity
[X] Subsequent Report	[ ] Casing Repair	[ ] New Construction	[ ] Recomplete	[ ] Other _____
	[ ] Change Plans	[ ] Plug and abandon	[ ] Temporarily Abandon	_____
[ ] Final Abandonment Notice	[ ] Convert to Injection	[ ] Plug back	[X] Water Disposal	_____

13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

Required Information for the Disposal of Produced Water:

1) Name of formation producing water on lease: Bone Spring
2) Amount of water produced in barrels per day: 1200 BWPD
3) How water is stored on lease: 2 - 500 bbl fiberglass tanks
4) How water is moved to disposal facility: Trucked
5) Disposal Facility:
   a) Facility Operator Name: Mesquite SWD Inc.
   b) Name of facility or well name & number: Cedar Lake 36 State #1 (Order SWD-1275)
   c) Type of facility or well: WDW
   d) Location by 1/4, 1/4, Section, Township & Range: NESW, Sec 36-T17S-R30E

APPROVED
FEB 2 8 2014
JAMES A. AMOS
SUPERVISOR-EPS

14. I hereby certify that the foregoing is true and correct.

Name *(Printed/ Typed)*
Stormi Davis

Title:
Regulatory Analyst

Signature:

Date:
1/20/14

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by:

Title: Petroleum Engineer

Date: APR 0 7 2014

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office:

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitiousor fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

APR 0 7 2014